


**Section A - Accident Details**

Registration Number	SHB841J
Case Reference Number	TAX/09/20/2031
Registration Date	27/7/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	HAU YEE TONG JOSEPH
Type of Accident	Side Swipe
Accident Date and Time	12/9/2020 10:50 AM
Accident Reported Date and Time	14/9/2020 9:05 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108143
Special Instruction to ARC, if any	LEFT REAR PORTION
Prepared Date and Time	14/9/2020 11:03 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$756.00	\$200.00
Total Spare Part Cost	\$1,378.44	\$120.00
Total Other Cost	\$636.88	\$130.00
<b>TOTAL COST</b>	<b>\$3,109.32</b>	<b>\$650.00 (L/S)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	14/09/2020 4:30 PM	14/09/2020 3:09 PM
Signature		
Remarks		L/S, After paint photo.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/09/2020

User ID : PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2009-0341	Invoice Number	
Quotation Date	23.09.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	\$338.00	\$200.00
<b>Total Labour</b>	<b>\$338.00</b>	<b>\$200.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$756.00</b>	<b>\$200.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$186.88)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$636.88</b>	<b>\$130.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair R
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given X
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given X
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		61602-47091	FENDER RR/LH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given X
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given X
		65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given X
<b>Total</b>					<b>\$1,713.61</b>		<b>\$120.00</b>		

120.00 /  
 + 200.00 /  
 + 516.88 /  
 -----  
 836.88 /  
 - 20%  
 -----  
 669.50 /  
 45 \$650 /  
 2 days

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									