

Indra



ESTEEM PERFORMANCE PTE LTD

81k 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.
Tel : 6484 1221 Fax : 6484 7829
385 Sin Ming Drive (Inside Vicom) Singapore 575718.
Tel : 6753 2112 Fax : 6451 0394
Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Not Authorized
After
Repair
6/1/20

Repair Estimates

SLR 2280 H

Parts (a) Cost / List Price Items	\$ 15,043.92
Plus/Less 25%	\$ 3,760.98
Total of Cost / List	\$ 11,282.94
(b) Nett Price Items	
Less	
Total of Nett Item	
(c) Special Nett Items	
Total Parts Cost	
Labour	\$ 4,070.00
Total	\$ 15,352.94

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : CLK
Survey conducted on : 15/9/20 at

Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : 09 day(s)
- (c) Resurvey : Required / ~~Not Required~~
- (d) Excess : \$
- (e) Signature of surveyor : Le Date: 15/9/20



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SLR 2280 H

TOYOTA PRIUS

JTDKB3FU203563466

Submit By :

Year Manufacture :

Engine No. :

Cost / List

Carmen Lim

2017 Aug

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>CM</i>	1	\$2,561.60		✓
2	Front support panel centre <i>R</i>	1	\$338.50		X
3	Front support panel RH <i>R</i>	1	\$213.50		X
4	Headlamp panel RH <i>R</i>	1	\$89.20		✓
5	Front windscreen side garnish <i>CM</i>	1	\$105.50		
6	Front bumper <i>Sn</i>	1	\$450.80		X
7	Front bumper clip <i>na</i>	10	\$40.00		X
8	Front bumper side retainer RH <i>Sn</i>	1	\$77.00		X
9	RH wing mirror (arm)	1			
10	RH wing mirror (signal lamp) <i>Br</i>	1	\$1,374.20		✓
11	RH wing mirror (glass)	1			
12	RH wing mirror (cover) <i>my</i>	1	\$87.40		✓
13	RH front fender <i>Ry</i>	1	\$868.70		✓
14	RH front fender undershield <i>Sn</i>	1	\$176.50		X
15	RH front fender undershield clip <i>na</i>	10	\$25.00		X
16	RHF fender wording "HYBRID" <i>na</i>	1	\$45.17		✓
17	RH front hub cab <i>Sn</i>	1	\$195.62		X
18	RH front door <i>R</i>	1	\$1,226.70		X
19	RH front door hinge top <i>R</i>	1	\$78.34		X
20	RH front door hinge bottom <i>R</i>	1	\$78.34		X
21	RH front door lock <i>R</i>	1	\$428.40		X
22	RH front door checker <i>Sn</i>	1	\$156.79		X
23	RH front door weatherstrip <i>Sn</i>	1	\$198.49		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLR 2280 H
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU203563466

Submit By : Carmen Lim
 Year Manufacture : 2017 Aug
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RHF door glass <i>WT</i>	1	\$818.10		✓
25	RHF door glass outer moulding <i>WT</i>	1	\$122.95		✓
26	RHF door stand garnish	1	\$75.60		✓
27	RH rear door <i>R</i>	1	\$1,181.75		✓
28	RH rear door hinge top <i>R</i>	1	\$78.34		X
29	RH rear door hinge bottom <i>R</i>	1	\$78.34		X
30	RH rear door lock <i>R</i>	1	\$411.70		X
31	RH rear door checker <i>Sn</i>	1	\$156.79		X
32	RH rear door weatherstrip <i>Sn</i>	1	\$178.40		X
33	RH rear door glass <i>WT</i>	1	\$450.90		✓
34	RHR door glass outer moulding <i>WT</i>	1	\$111.61		✓
35	RH rear door outer handle <i>R</i>	1	\$107.40		X
36	RH rear fender <i>R</i>	1	\$881.60		✓
37	Rear bumper <i>R</i>	1	\$411.64		X
38	Rear bumper clip <i>WT</i>	10	\$40.00		X
39	Rear bumper side retainer RH <i>Sn</i>	1	\$112.70		X
40	Tail lamp RH - UPPER <i>CM</i>	1	\$498.75		✓
41	Tail lamp RH - LOWER	1	\$511.60		?
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221

Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112

Fax : 6451 0394

Co. Reg No. : 200005485N

GST Reg No. : 20-0005485-N

Labour

Vehicle No. : **SLR 2280 H**

Submit By : **Carmen Lim**

Make & Model : **TOYOTA PRIUS**

Year of Manufacture : **2017 Aug**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,BONNET, RH WINDSCREEN PILLAR,RHF DOOR,RHR DOOR,RHR FENDER,REAR BUMPER)	\$1,400.00	1000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,BONNET, RH WINDSCREEN PILLAR,RHF DOOR,RHR DOOR,RHR FENDER,REAR BUMPER)	\$1,800.00	1200
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	80
5	To tuff coat.	\$150.00	90
6	To remove & refit inner seat & upholstery to assist work load.	\$250.00	100
7	To do wheel alignment <i>nn</i>	\$120.00	X
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and quote accordingly Acknowledged by Repairer Signature: Date:			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.