

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 97384383

TP III
 Xiao Tang

ESTIMATE

Repair Code : CLM16420

Date in : 12/09/2020

Vehicle Num. : SLH5925P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218320/LEB5918332

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR CLEANER BOX ASSY <i>check</i>	1	235.70	✓ 235.70
AIRBAG ECU <i>Activated</i>	1	980.00	✓ 980.00
AIRBAG IMPACT SENSOR	1	150.00	✓ 150.00
ENGINE ECU <i>Not new</i>	1	2800.00	X 2,800.00
ENGINE MOUNTING BRACKET LH <i>X not new</i>	1	95.00	X 95.00
ENGINE MOUNTING BRACKET RH	1	98.00	X 98.00
ENGINE MOUNTING LH <i>torn</i>	1	335.00	✓ 335.00
ENGINE MOUNTING REAR <i>torn</i>	1	135.00	✓ 135.00
ENGINE MOUNTING RH <i>torn</i>	1	154.60	✓ 154.60
ENGINE UNDER COVER <i>deland</i>	1	96.80	✓ 96.80
ENGINE UNDER COVER SIDE L/R <i>LH deland</i>	2	65.00	65 130.00
FRONT AIRCON CONDENSER <i>Best</i>	1	568.10	✓ 568.10
FRONT AIRCON CONDENSER ALUMINIUM <i>Suction Pipe. Best</i>	1	195.00	✓ 195.00
FRONT AIRCON CONDENSER DISCHARGE PIPE <i>Best</i>	1	210.00	✓ 210.00
FRONT AIRCON FAN BLADE <i>not new</i>	1	57.70	X 57.70
FRONT AIRCON FAN COWLING <i>check</i>	1	125.00	✓ 125.00
FRONT AIRCON FAN MOTOR <i>change</i>	1	295.00	✓ 295.00
FRONT BATTERY BRACKET <i>Best</i>	1	18.50	✓ 18.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 97384383

ESTIMATE

Repair Code : CLM16420

Date in : 12/09/2020

Vehicle Num. : SLH5925P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218320/LEB5918332

FRONT BATTERY MANFUSE <i>new</i>	1	85.00	X	85.00
FRONT BATTERY TRAY <i>Deformed</i>	1	22.00	✓	22.00
FRONT BONNET <i>Distorted</i>	1	892.30	✓	892.30
FRONT BONNET HINGES L/R <i>Best</i>	2	48.50	✓	97.00
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	23.80	X	47.60
FRONT BONNET INNER SIDE MOULDING L/R <i>new</i>	2	37.50	X	75.00
FRONT BONNET INNER TOP MOULDING L/R	2	23.00	+	46.00
FRONT BONNET INSULATOR <i>torn</i>	1	122.30	✓	122.30
FRONT BONNET MECHANISM LOCK <i>Damaged</i>	1	95.00	✓	95.00
FRONT BUMPER <i>Distorted</i>	1	801.70	✓	801.70
FRONT BUMPER FOGLAMP BRACKET L/R <i>curled</i>	2	48.00	✓	96.00
FRONT BUMPER FOGLAMP GARNISH L/R <i>Deformed</i>	2	45.00	✓	90.00
FRONT BUMPER FOGLAMP L/R <i>curled</i>	2	327.70	✓	655.40
FRONT BUMPER LOWER GRILLE <i>curled</i>	1	77.50	✓	77.50
FRONT BUMPER LOWER LID <i>Distorted</i>	1	381.00	✓	381.00
FRONT BUMPER LOWER LID SPOILER <i>Distorted</i>	1	138.00	✓	138.00
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	321.00	✓	321.00
FRONT BUMPER REINFORCEMENT TOP MOULDING L/R <i>Deformed</i>	2	35.00	✓	70.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 97384383

ESTIMATE

Repair Code : CLM16420

Date in : 12/09/2020

Vehicle Num. : SLH5925P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218320/LEB5918332

FRONT BUMPER SIDE RETAINER L/R <i>Nec</i>	2	20.60	✓	41.20
FRONT BUMPER TOW HOOK COVER <i>Debond</i>	1	17.10	✓	17.10
FRONT CHASSIS LH SIDE MEMBER (INNER PANEL) <i>3 Repairs</i>	1	55.00	x	55.00
FRONT CHASSIS LH SIDE MEMBER (OUTER PANEL)	1	55.00	x	55.00
FRONT FENDER 'HYBRID' EMBLEM L/R <i>Nec</i>	2	58.00	✓	116.00
FRONT FENDER ARCH GARNISH L/R <i>cracked</i>	2	220.00	✓	440.00
FRONT FENDER INNER GARNISH (VERTICAL) L/R <i>Nec new</i>	2	48.00	x	96.00
FRONT FENDER INNER SHIELD COVER L/R <i>horn</i>	2	130.00	✓	260.00
FRONT FENDER L/R <i>RT Distorted, LH Repairs</i>	2	580.00	580	1,160.00
FRONT FUSE BOX COVER <i>Nec new</i>	1	27.50	+	27.50
FRONT FUSE BOX LH <i>cracked</i>	1	985.00	✓	985.00
FRONT GRILLE <i>Missing</i>	1	351.80	✓	351.80
FRONT GRILLE 'LOGO' EMBLEM <i>Missing</i>	1	23.40	✓	23.40
FRONT GRILLE CENTER BRACKET <i>Missing</i>	1	76.00	✓	76.00
FRONT GRILLE CHROME MOULDING <i>Missing</i>	1	98.00	✓	98.00
FRONT GRILLE OUTER COVER <i>Missing</i>	1	421.00	✓	421.00
FRONT GRILLE TOP GARNISH <i>Debond</i>	1	85.00	✓	85.00
FRONT HEADLAMP L/R <i>cracked</i>	2	1784.50	✓	3,569.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 97384383

ESTIMATE

Repair Code : CLM16420

Date in : 12/09/2020

Vehicle Num. : SLH5925P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218320/LEB5918332

FRONT HEADLAMP LOWER BRACKET L/R	LH Cashed	2	35.00	35	70.00
FRONT HEADLAMP SIDE BRACKET L/R	Not New	2	35.00	X	70.00
FRONT HORN L/R	LH Cashed	2	48.60	48.60	97.20
FRONT LH BODY EXTENSION MEMBER	Breiked	1	755.00	✓	755.00
FRONT OUTSIDE TEMPERATURE SENSOR	Damaged	1	98.00	✓	98.00
FRONT RESONATOR	Cashed	1	180.50	✓	180.50
FRONT RESONATOR TUBE	Not New	1	27.50	X	27.50
FRONT RH DOOR SIDE MIRROR	Not	1	794.50	✓	794.50
FRONT RH DOOR SIDE MIRROR COVER	Not New	1	80.00	+	80.00
FRONT SEAT BELT L/R	Activated	2	680.00	✓	1,360.00
FRONT STEERING AIRBAG	Activated	1	1605.00	✓	1,605.00
FRONT STEERING CLOCK SPRING SENSOR	Activated	1	289.90	✓	289.90
FRONT SUPPORT PANEL	Distorted	1	576.20	✓	576.20
FRONT SUPPORT PANEL INNER RUBBER STOPPER L/R	Not New	2	18.50	X	37.00
FRONT WASHER TANK	Rebld	1	75.00	✓	75.00
FRONT WASHER TANK MOTOR	Not New	1	59.60	X	59.60
FRONT WASHER TANK NECK	Not New	1	28.30	X	28.30
FRONT WHEEL HOUSING (INNER PANEL) L/R	Rjs	2	165.00	X	330.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 97384383

ESTIMATE

Repair Code : CLM16420

Date in : 12/09/2020

Vehicle Num. : SLH5925P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218320/LEB5918332

FRONT WHEEL HOUSING (OUTER PANEL) L/R	2	115.00	x	230.00
FRONT WINDSCREEN	1	1950.00	1280	1,950.00
FRONT WINDSCREEN MOULDING	1	168.30	✓	168.30
FRONT WIPER GARNISH	1	200.00	✓	200.00
GEAR BOX SENSOR	2	223.50	✓	447.00
GEAR BOX WIRE HARNESS	1	792.30	x	792.30
RADIATOR (AUTO)	1	1376.60	✓	1,376.60
RADIATOR BOTTOM MOUNTING L/R	2	14.50	✓	29.00
RADIATOR FAN BLADE	1	57.70	x	57.70
RADIATOR FAN COWLING	1	125.00	✓	125.00
RADIATOR FAN MOTOR	1	298.00	✓	298.00
RADIATOR SIDE GUIDE L/R	2	31.60	✓	63.20
RADIATOR SPARE TANK	1	62.50	✓	62.50
RADIATOR TOP MOUNTING L/R	2	10.50	✓	21.00
Subtotal before discount				31,023.50
Percentage discount 20%				6,204.70
Sub-total 1				24,818.80
ENGINE UNDER COVER CLIPS - SET	1	50.00	30	50.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 97384383

ESTIMATE

Repair Code : CLM16420

Date in : 12/09/2020

Vehicle Num. : SLH5925P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218320/LEB5918332

FRONT BATTERY <i>Dangd</i>	1	230.00	180	230.00
FRONT BONNET INSULATOR CLIPS - SET <i>rw</i>	1	60.00	30	60.00
FRONT BUMPER CLIPS - SET <i>rw</i>	1	50.00	30	50.00
FRONT FENDER ARCH GARNISH CLIPS L/R - SET <i>3 New</i>	2	30.00	✓	60.00
FRONT FENDER INNER SHIELD COVER CLIPS L/R - SET <i>✓</i>	2	30.00	✓	60.00
FRONT GRILLE CLIPS - SET <i>rw</i>	1	50.00	20	50.00
FRONT NUMBER PLATE <i>3 Dangd</i>	1	25.00	✓	25.00
FRONT NUMBER PLATE HOLDER <i>555</i>	1	50.00	30	50.00
FRONT WINDSCREEN SEALANT <i>rw</i>	1	80.00	60	80.00
FRONT WIPER GARNISH CLIPS - SET <i>Nec</i>	1	30.00	✓	30.00
Subtotal before discount			745.00	
Percentage discount 0%			0.00	
Sub-total 2			745.00	
Parts-total			25,563.80	

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change air bag, air-bag sensor, air-bag wire and resetting system.

To reset system after repair works

120 ~~150.00~~
 80 ~~120.00~~
 ✓ 280.00
 150 ~~400.00~~

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 97384383

ESTIMATE

Repair Code : CLM16420

Date in : 12/09/2020

Vehicle Num. : SLH5925P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218320/LEB5918332

To remove, reinstall windscreen. (to FR)

120. 150.00

To remove, install engine with transmission. (to FR)

350. 450.00

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

✓ 350.00

To road test driving, check and resetting wheel alignments system.

✓ 80.00

To remove, reinstall dashboard fascia, meter reading and etc. (to FR)

× 250.00

To re-spray painting on the front bonnet, front support panel, front fender (L/R), front bumper and front doors (L/R).

1600. 2,300.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

4810

1600 2,800.00

To apply anti-rust chemical on repaired and replaced panel.

80 120.00

Labour Total

7,450.00

Parts & Labour Total

33,013.80

*** This is a computer-generated document which requires no signature.***

page 7

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 24840.76.

2/S: 18K (Nett Value)
12 Days. ✓

Repair Limit: 18k