

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Sep 2020 15:00 Sendback Est	14 Sep 2020 15:13 S\$2,786.22	14 Sep 2020 19:11 Edit Adj Rpt	S\$1,600.00 Edit Estimates	S\$1,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CTPL , Co. Reg. No.: 1XXXXX821R		
Main Claimant:	CTPL , Co. Reg. No.: 1XXXXX821R		
Vehicle Reg. No.:	SHA4692B	Date of Loss:	10/09/2020 21:00 - :59 [44 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2004475	Policy/Cover Note No.:	ME000569 (TP, Fire & Theft) Coverage: 05/06/2020 - 04/06/2021
Vehicle Reg. No. (Insured):	PA6117M	Policy No. (Claimant):	
		Excess:	S\$2,500.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/09/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA4692B (M2004475)
[PA6117M]
TP
CTPL
Sep 10 2020 9:00PM
[CTPL]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports			1 per page	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
1	14/09/20 15:13	Repairer Estimates	1	Load HTM
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail Print
1	14/09/20 19:12	Accident Statement From:SC - Reg. No: PA6117M, Claimant: SUPER STEEL PTE LTD	1	Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	15/09/20 11:35	Adjuster Immediate Advice	1	Load HTM
Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	16/09/20 10:42	Odometer Reading	1	Load JPG
2	16/09/20 10:42	Chassis Number	1	Load JPG
3	16/09/20 10:42	General View	1	Load JPG
4	16/09/20 10:42	General View	1	Load JPG
5	16/09/20 10:42	General View	1	Load JPG
6	16/09/20 10:42	General View	1	Load JPG
7	16/09/20 10:42	General View	1	Load JPG
8	16/09/20 10:42	General View	1	Load JPG
9	16/09/20 10:42	General View	1	Load JPG
10	16/09/20 10:42	General View	1	Load JPG
11	16/09/20 10:42	General View	1	Load JPG
12	16/09/20 10:42	General View	1	Load JPG
13	17/09/20 21:59	After Repair Photo	1	Load JPG
14	17/09/20 21:59	After Repair Photo	1	Load JPG
15	17/09/20 21:59	After Repair Photo	1	Load JPG
Documentation			1 per page	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
1	14/09/20 15:14	E-filed GIA report	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI20009844/T1QF3S2**Date:** 21/09/2020REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ME000569	
Claimant Vehicle No :	SHA4692B	Insured Vehicle No :	PA6117M	
Date of Loss:	10/09/2020	Nature of Claim:	TP	Claim No: M2004475

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4692B	Engine No:	D4FDGU695429
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMHU097316
Reg. Date:	22/12/2016 (Man. Year: 2016)	Odometer:	379732 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,645.22	1,481.04	164.18	9.98
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,130.00	540.00	590.00	52.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,786.22	2,032.04	754.18	27.07
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	2,786.22	1,600.00	1,186.22	42.57
+ GST 7.00/7.00% (S\$)	195.04	112.00	83.04	42.58
Nett Amount (S\$)	2,981.26	1,712.00	1,269.26	42.57

INSPECTION

Date of Assignment:	14/09/2020	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	14/09/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Sep 2020)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA4692B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Deformed	1,106.00 FL	-	*1,106.00 FL
2	1		*REAR BUMPER BRACKET - LH / RH	Not Necessary	35.60 FL	-	*- FL
3	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 FS	-	*- FS
4	1		*REAR BUMPER MAT	Necessary	50.00 FS	-	*50.00 FS
5	1		*REARBUMPER ADVERTISEMENT	Necessary	100.00 FS	-	*100.00 FS
6	1		*TAILLAMP RH ASSY	Cracked	557.80 FL	-	*557.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,985.10	1,813.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	339.88	332.76
Total Parts (\$\$)	1,645.22	1,481.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	450.00	280.00
2	SPRAY PAINTING	New	500.00	200.00
3	CHECK LIGHTING	New	60.00	30.00
4	REMOVE /REFIX REVERSE SENSOR.	New	60.00	30.00
5	TUFF COATING	New	60.00	0.00
Gross Labour Cost (\$\$)			1,130.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >