

## PAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Sep 2020)  
 Part: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue: Merimen Singapore 1.0)  
 List: Repairer's (Price-denominated Standard List)  
 Code: ComfortDelGro Engineering Pte Ltd/SHA4692B/14/09/2020 15:13  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No.                                    | Qty | Part No. | Particulars                    | %Disc | %Depr | Amount              |
|----------------------------------------|-----|----------|--------------------------------|-------|-------|---------------------|
| 1                                      | 1   |          | *REAR BUMPER COVER             | 20.00 | 0.00  | de ✓ *1,106.00 FL   |
| 2                                      | 1   |          | *REAR BUMPER BRACKET - LH / RH | 20.00 | 0.00  | LH X RH X *35.60 FL |
| 3                                      | 1   |          | *REAR BUMPER REVERSE SENSOR    | 0     | 0.00  | nn x *135.70 FS     |
| 4                                      | 1   |          | *REAR BUMPER MAT               | 0     | 0.00  | nei ✓ *50.00 FS     |
| 5                                      | 1   |          | *REAR BUMPER ADVERTISEMENT     | 0     | 0.00  | nei ✓ *100.00 FS    |
| 6                                      | 1   |          | *TAIL LAMP RH ASSY             | 20.00 | 0.00  | CR ✓ *557.80 FL     |
| Sub Total (\$\$)                       |     |          |                                |       |       | 1,985.10            |
| - List Item Discount on L Items (\$\$) |     |          |                                |       |       | 339.88              |
| Total Parts (\$\$)                     |     |          |                                |       |       | 1,645.22            |

F=Franchise part. S=SpcNett. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA4692B/14/09/2020 15:13. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

1663.80  
 20% - 1331.04  
 SW - 150

# Estimates on Miscellaneous Items

Qty Particulars

Amount

## Miscellaneous Items

1 CD/TP Case (Insurer)

11.00

Sub Total (S\$)

✓ 11.00

## Estimates on Labour

No Particulars

Lab.Type

Amount

## Labour Items

1 PANEL BEATING

New 280 450.00

2 SPRAY PAINTING

New 200 500.00

3 CHECK LIGHTING

New 30 60.00

4 REMOVE /REFIX REVERSE SENSOR.

New 30 60.00

5 TUFF COATING

New 110 60.00

Gross Labour Cost (S\$) 540 1,130.00

ComfortDelGro Engineering Pte Ltd/SHA4692B/14/09/2020 15:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan/Min 97495744  
WP 14/9/2020 4pm  
- 2 days  
H/S Resurvey after repair.  
Hendrik

1331.04  
150  
11  
540  
2032.04  
4/5/1600 #  
- 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: