

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Cheong

Date: 29 Sep 2020

## **Preliminary Advice**

Vehicle No	: SKM4084H	Accident Date	: 11/09/2020
Make	: TOYOTA ISIS	Policy No.	: PNPV2018-00009818
Assignment Date	: 14/09/2020	Excess	: S\$750.00
Date of Inspection	: 15/09/2020	Est. Duration of Repair	: 0
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	52,000.00
COE / PARF Rebate	:S\$	35,620.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,380.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :