




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

-	Ref : CC6/TP20009856/Ues3q2	
FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883	Date : 08-12-2020	
ON BEHALF OF CORTEN INTERIOR SOLUTIONS PTE LTD	Code : TP130	

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SKU 9223Z
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	15/09/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE (A)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTNGF3DH908002003	Colour	SILVER
Odometer	114525	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	MICHELIN	6 mm
L/H Front Tyre	235/50 R18	MICHELIN	6 mm
R/H Rear Tyre	235/50 R18	MICHELIN	6 mm
L/H Rear Tyre	235/50 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/09/2020	Inspection Date	15/09/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------