



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL Ref : CS/SMO20009857/Usf3e2

50 RAFFLES PLACE  
#05-01/06  
SINGAPORE LAND TOWERSINGAPORE 048623

Date : 30-09-2020



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBC 3421J	<b>Veh. Inspected</b>	SLX 1865X
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2002573/AGC	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MELVIN YE YONG KANG	<b>Assign Date</b>	15/09/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI ELANTRA (A)	<b>c.c</b>	1591
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	KMHD841CMJU645318	<b>Colour</b>	GREY
<b>Odometer</b>	52256	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/50 R17	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	215/50 R17	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	215/50 R17	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	215/50 R17	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	31/08/2020	<b>Inspection Date</b>	15/09/2020
<b>Survey held at</b>	Blk 15 Kaki Bukit Road 4, Bartley Biz Centre #01-53		
<b>Repairer</b>	ZOOM AUTOWERKS PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**