

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

L/Bal.

mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 40616 Dep 10k XT model

29/9/20 4/5 \$3600 confirmed with Alan

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

FASTTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48, AUTO BAY
SINGAPORE 417883

LKK: Jasper

Not Authorized
LKK
15/9/20
1/s a 3600 / 3 days.

VEHICLE No: SJW 797U

1PC	FRONT BUMPER	600.00
1PC	FRONT BUMPER SIDE HOLDER N/S	35.00
1SET	FRONT BUMPER CLIPS	
1PC	FRONT BUMPER REINFORCEMENT	320.30
1PC	FRONT FOG LAMP O/S	325.00
1PC	FRONT FOG LAMP CHROME O/S	166.00
1PC	FRONT BUMPER SIDE GRILLE O/S	
1PC	FRONT BUMPER INNER BRACKET O/S	
1PC	FRONT FENDER O/S	
1PC	FRONT FENDER INNER SHIELD O/S	215.50
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	
1PC	FRONT FENDER OUTER PROTECTOR O/S	245.50
1PC	HEADLAMP O/S	2380.00
1PC	FRONT SUPPORT PANEL	

De / Deep cut	\$800.60	✓
sent	\$66.50	✓
net	\$50.00	✓
DD	\$755.00	✓
Che	\$650.00	✓
Scr	\$288.00	✓
Sen	\$105.00	X
nr	\$211.00	X
n	\$845.00	X
de/turn	\$366.00	✓
net	\$50.00	✓
net	\$365.00	✓
Che	\$2,880.00	✓
n	\$822.00	X
	\$8,254.10	

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	30
11	\$50.00	X
11	\$120.00	X
	\$800.00	400
	\$1,080.00	580
TOTAL	\$10,354.10	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p-4367.9
20%
3494.32
4504.32
3607