

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009874/KES3Q2
Date: 27/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800052265
Claimant Vehicle No :	SLN1834M	Insured Vehicle No :	GBE9447K
Date of Loss:	13/09/2020	Nature of Claim:	TP
		Claim No:	4261871737SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1834M		
Make & Model:	MERCEDES-BENZ E250, 1.8 Blue efficiency (A)	Engine No:	27186030569113
Reg. Date:	21/03/2013 (Man. Year: 2012)	Chassis No:	WDD2120472A698762
Colour:	Metallic Grey	Odometer:	198692 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,427.50	9,243.00	184.50	1.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,780.00	360.00	16.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,567.50	11,023.00	544.50	4.71
Approved Total (Overridden) (S\$)		9,000.00		

(S\$)	11,567.50	9,000.00	2,567.50	22.20
+ GST 7.00/7.00% (S\$)	809.73	630.00	179.73	22.20
Nett Amount (S\$)	12,377.23	9,630.00	2,747.23	22.20
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		10,438.00		

INSPECTION

Date of Assignment: 15/09/2020

Date Inspected: 24/09/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,945.00 FN	*1,945.00 FN
2	1		*REAR BUMPER REINFORCEMENT	Bent	913.00 FN	*913.00 FN
3	1		*REAR BUMPER LOWER SKIRT	Distorted / Cut	598.00 FN	*598.00 FN
4	1		*REAR BUMPER TOW COVER	Missing	71.00 FN	*71.00 FN
5	2		*SEAT SHIELD REST	Activated / Jammed	2,830.00 FN	*2,830.00 FN
6	1		*REAR BOOT LOGO	Necessary	54.00 FN	*54.00 FN
7	1		*REAR BOOT EMBLEM E250	Necessary	90.00 FN	*90.00 FN
8	1		*REAR BOOT EMBLEM 7G-TRONIC	Necessary	85.00 FN	*85.00 FN
9	1		*REAR BOOT INNER RUBBER	Serviceable	205.00 FN	*- FN
10	2		*REVERSE SENSORS	Shorted	636.00 FN	*636.00 FN
11	2		*TAILLAMPS	Cracked / Cut	1,330.00 FN	*1,330.00 FN
12	1		*REAR PANEL	Bent	1,395.00 FN	*1,395.00 FN
13	1		*REAR SPARE TYRE COMPARTMENT	Cracked	323.00 FN	*323.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$)	10,475.00	10,270.00
- Nett Item Discount on N Items 10.00/10.00% (\$)	1,047.50	1,027.00
Total Parts (\$)	9,427.50	9,243.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESET FRT SEAT HEAD REST SYSTEM	New	180.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,REAR REFLECTOR,CUT ,WELD & RENEW REAR END PANEL ,REAR SPARE TYRE COMPARTMENT ,KNOCK & REPAIR REAR BOOT & REALIGN THE SAME	New	1,000.00	800.00
3	PUTTY & RESPRAY ON REAR BOOT ,REAR PANEL ,REAR SPARE TYRE COMPARTMENT ,REAR BUMPER & REAR AFFECTED AREAS	New	900.00	800.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			2,140.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >