

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
TEL: 90079247

TO	: <i>ALG</i>	DATE	: <i>12/09/2020</i>
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: <i>SJQ 1561H</i>		
VEHICLE MODEL	: <i>Toyota Allion</i>		
CHASSIS NO	: <i>WZT 2603039347</i>		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XAVIER / 90079247	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>deformed</i>	1	\$ 968.40	\$ 968.40
2	REAR BUMPER SIDE HOLDER <i>New</i>	2	\$ 45.10	\$ 90.20
3	REAR BUMPER REFLECTOR <i>RH cracked</i>	2	\$ 97.60	\$ 195.20
4	REAR END PANEL <i>Dented</i>	1	\$ 584.60	\$ 584.60
5	REAR END PANEL TOP GARNISH <i>deformed</i>	1	\$ 233.90	\$ 233.90
6	REAR END PANEL ANTENNA SENSOR <i>cracked</i>	1	\$ 157.40	\$ 157.40
7	TAILLAMP <i>cracked</i>	2	\$ 378.20	\$ 756.40
8	TAILLAMP PANEL <i>Repair</i>	2	\$ 235.20	\$ 470.40
9	BOOTLID <i>Dented</i>	1	\$ 951.60	\$ 951.60
10	BOOTLID LOCK <i>Damaged</i>	1	\$ 225.00	\$ 225.00
11	BOOTLID WEATHERSTRIPE <i>cut</i>	1	\$ 229.10	\$ 229.10
12	TOYOTA LOGO <i>3 New</i>	1	\$ 48.00	\$ 48.00
13	ALLION EMBLEM <i>3 New</i>	1	\$ 55.00	\$ 55.00
14	SPARE TYRE PANEL TOP COVER <i>deformed</i>	1	\$ 292.80	\$ 292.80
15	REAR EXHAUST PIPE <i>3 New</i>	1	\$ 781.80	\$ 781.80
16	REAR EXHAUST PIPE MOUNTING <i>3 New</i>	1	\$ 39.00	\$ 39.00

TOTAL PRICE: \$ 6,078.80
LESS 25% \$ 1,519.70
SUB TOTAL PRICE: \$ 4,559.10

4680
357.50

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>3 New</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>3 New</i>	1	\$ 30.00	\$ 30.00

3	REAR BUMPER CLIPS <i>Neu</i>	1 SET	\$ 50.00	\$ 50.00	<i>30</i>
4	REVERSE SENSOR <i>Damaged</i>	1 SET	\$ 280.00	\$ 280.00	<i>200</i>
5	REAR END PANEL TOP GARNISH CLIPS <i>Neu</i>	1 SET	\$ 20.00	\$ 20.00	<i>✓</i>
6	REAR END PANEL SEALANT <i>Neu</i>	1 SET	\$ 60.00	\$ 60.00	<i>✓</i>
7	TAILLAMP SPONGE GASKET <i>Neu</i>	2	\$ 20.00	\$ 40.00	<i>✓</i>
			TOTAL :	\$ 510.00	

350

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	<i>900</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>900</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>80</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
6	TO REMOVE AND REFIT UPHOLSTERY	\$ 150.00	<i>80</i>	
7	TO REMOVE AND REFIT EXHAUST PIPE	\$ 150.00	<i>X</i>	
8	TO TRANSFER BOOTLID FITTINGS	\$ 150.00	<i>80</i>	
9	TO REMOVE AND REFIT CAMERA	\$ 100.00	<i>50</i>	
		TOTAL:	\$ 3,250.00	

2170

ESTIMATE REPORT

TOTAL PARTS COST: \$ 5,069.10

TOTAL LABOUR COST: \$ 3,250.00

TOTAL REPAIR COST: \$ 8,319.10

total: 6037.5
L/s: 4.8K.
06 Days.

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: