

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 15-Sep-20

INSURANCE: AlG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHB 2343 S

Description	Qty	List Price	Amount	
Front Fender(LH) <i>Dent</i>	1	\$ 490.70	\$ 490.70	✓
Frt Door(LH) <i>Dent</i>	1	\$ 1,797.20	\$ 1,797.20	✓
Front Door Protector(LH) <i>cut</i>	1	\$ 186.20	\$ 186.20	✓
Rear Door (LH) <i>Dent</i>	1	\$ 1,789.90	\$ 1,789.90	✓
Rear Door Hinge Lower (LH) <i>HH</i>	1	\$ 170.50	\$ 170.50	X
Rear Door Protector(LH) <i>BT</i>	1	\$ 166.20	\$ 166.20	✓
Door Centre Pillar Outer (LH) <i>Dent</i>	1	\$ 3,764.90	\$ 3,764.90	✓
Rocker Panel Outer Garnish <i>cut</i>	1	\$ 715.60	\$ 715.60	✓
Rear Bumper <i>cut</i>	1	\$ 459.40	\$ 459.40	✓
Rear Bumper Side retainer (LH) <i>src</i>	1	\$ 85.80	\$ 85.80	X
Rear Bumper Cover Clips <i>Hec</i>	1	\$ 22.00	\$ 22.00	✓
Rear Bumper Side Under(LH) <i>HH</i>	1	\$ 123.10	\$ 123.10	X
Rear Fender(LH) <i>Dent</i>	1	\$ 1,768.30	\$ 1,768.30	✓
Rear Tyre Rim (LH) <i>HH</i>	1	\$ 1,124.20	\$ 1,124.20	X
Rear Wheel Hup-Cap (LH) <i>cut</i>	1	\$ 346.40	\$ 346.40	✓
Rear Wheelbearing & Hub assy <i>2 Down</i>	1	\$ 554.00	\$ 554.00	✓
Rear Trailing Arm(LH) <i>2 distal</i>	1	\$ 265.40	\$ 265.40	✓
Rear Assist (LH) <i>2 distal</i>	1	\$ 227.90	\$ 227.90	✓
Rear shock Absorber(LH) <i>2 distal</i>	1	\$ 230.50	\$ 230.50	✓
Rear Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 133.10	\$ 133.10	X
Rear Absorber stopper (LH) <i>HH</i>	1	\$ 137.60	\$ 137.60	X
Rear Absorber Cover (LH) <i>HH</i>	1	\$ 175.60	\$ 175.60	X
Rear Crossmember <i>2 distal</i>	1	\$ 1,468.70	\$ 1,468.70	✓
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30	X
Stabilizer Link (LH) <i>HH</i>	1	\$ 147.30	\$ 147.30	X
Rear Upper Arm(LH) <i>2 distal</i>	1	\$ 239.50	\$ 239.50	✓
Rear Lower Arm(LH) <i>2 distal</i>	1	\$ 393.10	\$ 393.10	✓
Rear Knuckle Arm (LH) <i>2 distal</i>	1	\$ 538.10	\$ 538.10	✓
			\$ -	
SUB TOTAL			\$ 17,908.50	
LESS 20%			\$ 3,581.70	
DISCOUNTED TOTAL			\$ 14,326.80	
Emblem-Blue Drive (LH) <i>Hec</i>	SN 1	\$ 27.00	\$ 27.00	✓
Front Door City Cab Logo (LH) <i>Hec</i>	SN 1	\$ 75.00	\$ 75.00	✓
Front Door Comfort Logo (LH) <i>Hec</i>	SN 1	\$ 75.00	\$ 75.00	✓
Rear Door Comfortdelgro & Apps Sticker(LH) <i>Hec</i>	SN 1	\$ 80.00	\$ 80.00	✓
Rear Tyre(LH) <i>HH</i>	SN 1	\$ 216.00	\$ 216.00	X
SUB TOTAL			\$ 473.00	

Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	1000/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	900/-
Wiring Charge	1	\$140.00	\$140.00	44
Tuff Kote	1	\$160.00	\$160.00	40/-
Towing Charge	1	\$80.00	\$80.00	44
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00	44
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00	150/-
Re-set Rear ABS System	1	\$400.00	\$400.00	44
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System	1	\$200.00	\$200.00	44
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System	1	\$200.00	\$200.00	44
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	180/-
TOTAL LABOUR				\$5,130.00
ESTIMATE TOTAL				\$ 19,929.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

15/09/2020 @ 1700hrs

N/A Auction

Part by Part. 7 days.

you

Photo of car

LKK Auto

with damaged parts.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 21-Sep-20

INSURANCE: AIG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHB 2343 S (S)

Description	Qty	List Price	Amount
Front Wheel Cap (LH) <i>cut</i>	1	\$ 289.80	\$ 289.80
SUB TOTAL			\$ 289.80
LESS 20%			\$ 57.96
DISCOUNTED TOTAL			\$ 231.84

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Ryan

2kk Ando

S