



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2008000  
INV Date 27/11/2020  
Reference CC3/CTI20009884/T1es3q2  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 7213R  
Insured Veh. SLN 5477J  
Claim No. SNM20D203357  
Policy No. DMPCSN3059841900  
Accident Date 12/09/2020  
Inspection Date 14/09/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20009884/T1es3q2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-11-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLN 5477J	<b>Veh. Inspected</b>	SHD 7213R
<b>Policy No.</b>	DMPCSN3059841900	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM20D203357	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	14/09/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA PRIUS	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	JTDKB3FU903537723	<b>Colour</b>	BLUE
<b>Odometer</b>	487307	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	DAVANTI	6 mm
<b>L/H Front Tyre</b>	195/65 R15	DAVANTI	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	DAVANTI	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	DAVANTI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	12/09/2020	<b>Inspection Date</b>	14/09/2020
<b>Survey held at</b>	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7213R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT DOOR RH	BENT	1,264.00	1,264.00
	LESS 25% DISCOUNT		-316.00	-316.00
			948.00	948.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT DOOR COMFORTDELGRO RH (SN)	CUT	75.00	75.00
1	REAR DOOR APPS RH (SN)	NECESSARY	80.00	80.00
			155.00	155.00
<b><u>LABOUR</u></b>				
	PANEL BEATING-REAR DOOR RH.		350.00	320.00
	SPRAYPAINT AFFECTED AREAS.		500.00	400.00
	TUFF COAT ON AFFECTED PARTS.		60.00	30.00
	TRANSFER OF DOOR.		120.00	60.00
			1,030.00	810.00
<b>GRAND TOTAL</b>			<b>2,133.00</b>	<b>1,913.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,550.00</b>

Report Ref No. CC3/CTI20009884/T1es3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 7213R

INSPECTION






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 7213R

RE-INSPECTION

