

## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 17/09/2020 : CatherineLee User ID

Section A - Accident Details					
Registration Number	SMB1415R				
Case Reference Number	BUS/09/20/1007				
Registration Date	6/1/2014				
Company Type	SMRT Buses Ltd				
Make	MAN				
Model	A22				
Name of Driver	Ooi Lay Tin				
Type of Accident	Side Swipe				
Accident Date and Time	8/9/2020 11:56 AM				
Accident Reported Date and Time	8/9/2020 1:45 PM				
Is Surveyor Required?	Yes				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number	24108124				
Special Instruction to ARC,if any	SMB1415R-RIGHT CENTER PORTION SLQ5907U (TP) INSURED WITH				
Prepared Date and Time	11/9/2020 11:18 AM				
Chassis Number	WMAA22ZZ3D7001994				
Mileage					
Work Shop					
Repair Completion Date and Time					

	Section B - Summary of Rep	pair Estimates				
Summary of Repair Estimates						
	Quotation from ARC	Adjusted by Surveyor, if applicable				
Total Labour Cost	\$1,590.00	\$1,060.00				
Total Spray Cost	\$1,388.00	\$1,048.00				
Total Spare Part Cost	\$160.00	\$160.00				
Total Other Cost	\$0.00	\$0.00				
TOTAL COST	\$3,138.00	\$2,268.00				
Lump Sum Total	\$3,150.00	\$2,250.00				
Number of Repair Days	6.0	3.0				
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)				
ARC / Surveyor Sign Off Date	11/09/2020 11:25 AM	11/09/2020 3:54 PM				
Signature		5				
Remarks						

Section C - Quotation and Accident Invoice Details						
Quotation Number		Invoice Number				
Quotation Date		Invoice Date				
Invoice Amount		Prepared Date				

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey beforester spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• That party survey is on a "Writhout Prejudice" basis
• No litegal modification(s) is allowed
• No litegal modification(s) in allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 17/09/2020 User ID : CatherineLee

			Section	on D - Detai	s of Repair E	stimates				
Part 1 - Labou	ır Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00				\$1,060.00			
			\$1,590.00				\$1,060_00			
Part 2 - Spray	/ Painting & Pa	nel Beating Rela	ited Works						<del></del>	
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$1,388,00				\$1,048.00		
	inting & Panel E	Seating		\$1,388.00				\$1,048.00		
Part 3 - Other	Costs = Accide	ent and Accident	t Repair Related Expens	se						
Job Scope	Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Co	sts									
Part 4 - Spare	Parts / Materia	al Usage								
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
6009987	BODY RH	A01001-CW568	PANEL,SIDE:R6,FOR MAN A22 BUS	1,00	\$1,776 <b>.</b> 80	100,00	\$0 <b>.</b> 00	Repair	Repair 🗸 🤾	
6009988	BODY RH	A01001-CW567	PANEL,SIDE:R7,FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0 <b>.</b> 00	Repair	Repair X K	
6009989	BODY RH	A01001-CW566	PANEL,SIDE:R8,FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	Repair X C	
6009990	BODY RH	A01001-CW565	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	Repair XI	
6009991	BODY RH	4000F06 <del>-</del> ACCE4526	PANEL,SIDE:R10,FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	Repair X R	
6010330			WHEEL ARCH TRIM	1.00	\$124.20	100.00	\$0 <b>.</b> 00	Repair	Repair X R	
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1,00	\$974.70	100,00	\$0 <b>.</b> 00	Repair	Repair XR	
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Rep <b>l</b> ace	Replace / NeC	
Total			_		\$5,195,30		\$200,00		300 030000-1110-0-	
Added Spare	Parts / Materia	l Usage After Su	rveyor Signed off							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Tota										

45 \$ 2,250 3days