




## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 11/09/2020

User ID : BoonChewTay

### Section A - Accident Details

Registration Number	SMB1415R
Case Reference Number	BUS/09/20/1007
Registration Date	6/1/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Ooi Lay Tin
Type of Accident	Side Swipe
Accident Date and Time	8/9/2020 11:56 AM
Accident Reported Date and Time	8/9/2020 1:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1415R-RIGHT CENTER PORTION SLQ5907U (TP) INSURED WITH 
Prepared Date and Time	11/9/2020 11:18 AM
Chassis Number	WMAA22ZZ3D7001994
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$1,388.00	\$0.00
Total Spare Part Cost	\$160.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$3,138.00</b>	<b>\$0.00</b>
Jump Sum Total	\$3,150.00	\$0.00
Number of Repair Days	6.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	11/09/2020 11:25 AM	
Signature		<input checked="" type="checkbox"/>
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number 83685592
Estimator Telephone Number : 68662823
Accident Reporting Number 68662872

Date Generated : 11/09/2020

User ID : BoonChewTay

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	1,060.
Total Labour	\$1,590.00	

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,388.00	1048.
Total Spray Painting & Panel Beating	\$1,388.00	

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
009987	BODY RH	A01001-CW568	PANEL, SIDE R6, FOR MAN A22 BUS	1.00	\$1,776.80	100.00	\$0.00	Repair	XK
009988	BODY RH	A01001-CW567	PANEL, SIDE R7, FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0.00	Repair	XK
009989	BODY RH	A01001-CW566	PANEL, SIDE R8, FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	XK
009990	BODY RH	A01001-CW565	PANEL, SIDE R9 WITH FRAME, FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	XK
009991	BODY RH	4000F06-ACCE4526	PANEL, SIDE R10, FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	XK
010330			WHEEL ARCH TRIM	1.00	\$124.20	100.00	\$0.00	Repair	XK
010062	Body	F01001-CW273	COVER REAR TAIL LAMP, RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	XK
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Replace	NEC
Total					\$5,195.30		\$200.00		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair dy - 3 days

L/S.

After paint photo

Sin Pin (Lkk)

11/09/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: