

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0664/2020/NS
DATE : 15-Sep-20
WIP : 49410

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

14 days exclude 2 Sunday -

Jy - 04 Dec 20

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LIM KIM HEONG
ADDRESS : BLK 552 PASIR RIS STREET 51
#13-83
SINGAPORE 510552
TELEPHONE : HP +65 96781621
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800075552-02
VEHICLE NO : SGB 9029 R
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 28/06/2018
ENGINE NO : CVK 061907
CHASSIS NO : WAUZZZF46JA170965
MILEAGE : 33643KM
DATE IN : 15-Sep-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Sep-20
PLACE OF ACCIDENT : SWAN LAKE AVE


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGB 9029 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00 \$	480.00
2	TO DISMANTLE AND RENEW FRONT AIR COND PIPES. TO VACUUM AND REGAS AIR COND SYSTEM.	S/N \$	480.00 \$	480.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00 \$	250.00
4	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY.	S/N \$	350.00 \$	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,450.00 \$	1,000.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR.	\$	3,500.00 \$	2,200.00
7	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00 \$	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 \$	192.00
TOTAL LABOUR CHARGES		:	\$ 8,082.00	\$ 5,162.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 9029 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER		\$	2,171.00	\$ 1,736.80
2	FRONT BUMPER FIXING PARTS		\$	282.00	
3	FRONT BUMPER SECURING STRIP	2	\$	70.00	\$ 27.84
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$	208.00	
5	FRONT BUMPER AIR GUIDE - LH		\$	62.00	
6	FRONT BUMPER AIR GUIDE GRILLE - LH		\$	361.00	
7	FRONT BUMPER CARRIER		\$	795.00	
8	FRONT BUMPER FOAM FILLER PIECE		\$	123.00	
9	FOAM FILLER PIECE COVER		\$	126.00	
10	FRONT BUMPER GUIDE SECTION - LH		\$	36.00	\$ 28.48
11	LOCK CARRIER BRACKET		\$	136.00	
12	LOCK CARRIER BRACKET SUPPORT - LH / RH	2	\$	56.00	
13	CAUTION SIGN STICKER	NEC	\$	14.00	
14	AIRCON STICKER	NEC	\$	8.00	
15	HORN - LH HIGH TONE		\$	124.00	
16	SPRING SHACKLE - LH		\$	29.00	
17	FRONT PARKING AID SENSOR	2		TBC	
18	FRONT PARKING AID SEAL RING	4	\$	14.00	
19	FRONT FENDER - LH		\$	758.00	\$ 606.00
20	FRONT FENDER ATTACHMENT PARTS		\$	200.00	
SUB TOTAL SPARE PARTS		:	\$	5,573.00	\$ 2,399.12

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 9029 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
		<i>c/f</i>		\$	2,399.12
21	FRONT FENDER CLOSING ELEMENT - LH	\$	49.00	\$	39.20
22	FRONT FENDER BRACKET - LH	\$	35.00	\$	27.60
23	DEFORMATION ELEMENT BRACKET - LH	\$	49.00	\$	38.80
24	FRONT FENDER BRACKET	\$	31.00	\$	24.80
25	FRONT FENDER BRACKET	\$	33.00		
26	FRONT FENDER BRACE - LH	\$	117.00	\$	93.60
27	FRONT FENDER CLOSING ELEMENT - LH	\$	33.00		
28	WHEEL HOUSING LINER - LH	\$	237.00	\$	189.20
29	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	90.00		
30	WHEEL SPOILER	\$	73.00	\$	57.76
31	WHEEL SPOILER TRIM - LH	\$	35.00		
32	STONE CHIP GUARD - LH	\$	50.00	\$	39.92
33	TOP FENDER LEDGE COVER - UPPER	\$	31.00	\$	24.40
34	TOP FENDER LEDGE COVER - LOWER	\$	23.00	\$	17.68
35	BONNET IMPACT PROTECTION - CENTRE	\$	27.00	\$	21.52
36	BONNET IMPACT PROTECTION - LH	\$	28.00	\$	21.84
37	BONNET IMPACT PROTECTION - RH	\$	27.00	\$	21.52
38	FENDER TOP INNER COVER - LH	\$	61.00	\$	48.24
39	LED HEADLIGHT - LH	\$	7,693.00	\$	6,154.40
40	LIFT CYLINDER - LH	\$	208.00		
SUB TOTAL SPARE PARTS		:	\$ 8,930.00	\$	9,219.60

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGB 9029 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
		<i>c/f</i>		\$	9,219.60
41	LIFT CYLINDER CORRUGATED PIPE		\$ 92.00		
42	REFRIGERANT LINE		\$ 165.00	\$	131.60
43	REFRIGERANT LINE		\$ 245.00	\$	196.00
44	REFRIGERANT LINE		\$ 336.00		
45	REFRIGERANT PIPE		\$ 517.00	\$	413.20
46	EXTERIOR MIRROR MOUNTING - LH		\$ 1,077.00		
47	MIRROR CAP - LH		\$ 261.00		
48	MIRROR GLASS - LH		\$ 1,196.00		
49	FRONT ALUMINIUM RIM - LH		\$ 684.00		
50	FRONT TYRE - LH	S/N	\$ 265.00	\$	265.00
51	SUNDRIES		\$ 300.00	\$	40.24
TOTAL SPARE PARTS		:	\$ 19,641.00	\$	10,265.64
TOTAL LABOUR CHARGES		:	\$ 8,082.00	\$	5,162.00
GRAND TOTAL		:	\$ 27,723.00	\$	15,427.64

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

BL-06/11/20