



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0659/2020/NS
DATE : 14-Sep-20
WIP : 49434

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : PREMIUM AUTOMOBILES PTE LTD
ADDRESS : 55 UBI ROAD 1
SINGAPORE 408699
TELEPHONE : OFF +65 66900293
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SMS 4915 E**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 27/2/2020
ENGINE NO : DLH 066820
CHASSIS NO : WAUZZZF2XLN013143
MILEAGE : 3296KM
DATE IN : 14-Jun-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Sep-20
PLACE OF ACCIDENT : MIDDLE ROAD

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 4915 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER. ✓	\$ 2,200.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,672.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 4915 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>Disbld</i>		\$	2,547.00 ✓	2037.60
2 FRONT BUMPER FIXING PARTS <i>Not nec</i>		\$	643.00 +	
3 FRONT BUMPER CLOSING ELEMENT - CENTRE <i>Disbld</i>		\$	220.00 + ✓	175.60
4 FRONT BUMPER ADAPTER - LH <i>Disbld</i>		\$	39.00 ✓	30.88
5 FRONT BUMPER REINFORCEMENT - LH <i>Not nec</i>		\$	110.00 <i>Not nec</i>	
6 FRONT BUMPER GRILLE - LOWER CENTRE <i>Not nec</i>		\$	151.00 +	
7 FRONT BUMPER CLOSING ELEMENT - LOWER <i>Not nec</i>		\$	208.00 +	
8 FRONT BUMPER SPOILER <i>Not nec</i>		\$	249.00 +	
9 FRONT BUMPER AIR GUIDE GRILLE - LH <i>Disbld</i>		\$	429.00 ✓	343.20
10 RADIATOR AIR GUIDE - LH <i>Disbld</i>		\$	28.00 + ✓	22.32
11 RADIATOR AIR GUIDE - LH <i>Not nec</i>		\$	21.00 +	
12 RADIATOR GRILLE <i>Not nec</i>		\$	2,192.00 +	
13 RADIATOR GRILLE COVER <i>Not nec</i>		\$	54.00 +	
14 CONNECTOR HOUSING BRACKET - LH <i>Not nec</i>		\$	28.00 +	
15 FRONT PARKING AID SENSOR <i>Not nec</i>			TBC +	
16 FRONT PARKING AID SEAL RING <i>Not nec</i>	4	\$	14.00 +	
17 FRONT BUMPER FOAM FILLER PIECE <i>Cracked</i>		\$	223.00 ✓	178.40
18 FRONT BUMPER CARRIER <i>Not nec</i>		\$	960.00 +	
19 FRONT BUMPER SUPPORT <i>Not nec</i>	2	\$	59.00 +	
20 FRONT BUMPER BRACKET - LH <i>Not nec</i>		\$	54.00 +	
SUB TOTAL SPARE PARTS	:	\$	8,229.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 4915 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 FRONT BUMPER GUIDE SECTION - LH <i>Damaged</i>		\$	44.00 ✓	34.75
22 FRONT BUMPER COVER <i>Not in</i>		\$	124.00 +	
23 PEDESTRIAN PROTECTION WARNING SIGN <i>Not in</i>	NEC	\$	14.00 +	
24 CAUTION SIGN STICKER <i>Not in</i>	NEC	\$	14.00 +	
25 FRONT FENDER - LH <i>Dented</i>		\$	1,451.00 ✓	1160.80
26 FRONT FENDER BRACE - LH <i>Not in</i>		\$	117.00 X	
27 FRONT FENDER BRACKET - LH UPPER <i>Not in</i>		\$	43.00 X	
28 FRONT FENDER ATTACHMENT PARTS <i>Not in</i>		\$	42.00 X	
29 WHEEL HOUSING LINER - LH <i>torn</i>		\$	272.00 ✓	217.20
30 WHEEL SPOILER - LH <i>Not in</i>		\$	164.00 X	
31 STONE CHIP GUARD - LH <i>Not in</i>		\$	50.00 ✓	39.92
32 HEADLIGHT MOUNTING - LH <i>Not in</i>		\$	117.00 X	
33 LED HEADLIGHT - LH <i>Not in</i>		\$	4,469.00 ✓	3575.20
34 LOCK COVER <i>Not in</i>		\$	43.00 +	
35 FENDER TOP LEDGE SUPPORT - LH <i>Not in</i>		\$	35.00 +	
36 RADIATOR AIR GUIDE - LH <i>Not in</i>		\$	38.00 +	
37 RADIATOR AIR GUIDE - UPPER <i>Not in</i>		\$	30.00 +	
38 FRONT NO PLATE <i>Not in</i>	S/N	\$	60.00 +	
39 SUNDRIES <i>Not in</i>		\$	300.00 X	
TOTAL SPARE PARTS	:	\$	15,656.00	
TOTAL LABOUR CHARGES	:	\$	5,672.00	
GRAND TOTAL	:	\$	21,328.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME

:

Adrian Lim

SURVEYED DATE

:

15/09/20

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT