

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

14-Sep-20

## ESTIMATE REPAIR BILL FOR MAZDA 3 REGN NO: SKF 5104 P

1 pc	Rear bumper	\$	799.60 <i>de ✓</i>
1 pc	Rear bumper n/s side bracket	\$	29.00 <i>?</i>
1 pc	Rear n/s lower arm	\$	299.00 <i>?</i>
1 pc	Rear n/s shock absorber	\$	373.00 <i>?</i>
2 pcs	Rear n/s upp arm <i>?</i>		
1 pc	Rear n/s trailing arm <i>?</i>		
1 pc	Rear n/s rim <i>dd ✓</i>		
<hr/>			
		Less 20%	\$ -
			<hr/>
			\$ -
<hr/>			
<b>S/NETT</b>			
1 pc	Rear bumper clips	\$	48.00 <i>20 net ✓</i>
	Sundry	\$	50.00
	To dismantle and replace Rear o/s undercarriage	\$	250.00 <i>150? plus</i>
	To check for Rear wheel alignment	\$	80.00 <i>provide report ✓</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same rear n/s fender	\$	650.00 <i>400.</i>
	To putty and spray painting on rear bumper, rear n/s fender	\$	800.00 <i>600.</i>
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 <i>30</i>
		<hr/>	
		\$	1,698.00

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

Tanji 97415349  
WP

Lumpsum, Resurvey after repair  
3 days  
tanji@lkkauto.com

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: