

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Sep-20

ESTIMATE REPAIR BILL FOR MAZDA 3 REGN NO: SKF 5104 P

1 pc	Rear bumper	\$	799.60
1 pc	Rear bumper n/s side bracket	\$	29.00
1 pc	Rear n/s lower arm	\$	299.00
1 pc	Rear n/s shock absorber	\$	373.00
2 pcs	Rear n/s upp arm		
1 pc	Rear n/s trailing arm		
1 pc	Rear n/s rim		

Less 20%

\$	-
\$	-

S/NETT

1 pc	Rear bumper clips	\$	48.00
	Sundry	\$	50.00
	To dismantle and replace Rear o/s undercarriage	\$	250.00
	To check for Rear wheel alignment	\$	80.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same rear n/s fender	\$	650.00
	To putty and spray painting on rear bumper, rear n/s fender	\$	500.00
	To apply rustproofing on the repaired and replaced panels.	\$	120.00
		\$	1,698.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.**