

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD  
 64 CECIL STREET  
 #04/#05 IOB BUILDING  
 SINGAPORE 049711  
 TEL: 63476100  
 ATTN: Motor Claim Department  
 WS Ref: TP/III/AMK  
 Claim Type: Third Party  
 Accident Date: 13/09/2020  
 TP Veh Reg No: SHC8735A

FAX: 62247743

*Not Authorized  
 11 Rep &  
 Resurvey After Painting*

Estimate No: ES2090719/AMK  
 Date: 14 Sep 2020  
 Policy No: 5115449990 DC  
 Veh Reg No: SKZ2997T  
 Make/Model: MAZDA 6  
 Chassis No: JM6GJ1032G0221227  
 Engine No: PY20666271  
 Reg. Date: 18/01/2016

*6 days*

## Estimate Repair Cost to Vehicle No :SKZ2997T

Description	U/Price	Quantity	List Price SS	Amount SS
<b>List Price</b>				
1 REAR LH FENDER	1,312.00	1 PC	1,312.00	✓
2 REAR LH FENDER QUARTER GLASS GARNISH	263.00	1 PC	263.00	✓
3 REAR LH DOOR	1,314.00	1 PC	1,314.00	✓
4 REAR LH DOOR INNER LOCK	249.00	1 PC	249.00	X
5 REAR LH DOOR POWER WINDOW MOTOR	156.00	1 PC	156.00	X
6 REAR LH DOOR POWER WINDOW MOTOR REGULATOR	149.00	1 PC	149.00	X
7 REAR LH DOOR FRAME STICKER	59.00	1 PC	59.00	✓
8 REAR WINDSCREEN GLASS MOULDING	118.00	1 SET	118.00	✓
9 REAR LH RIM 17"	1,341.00	1 PC	1,341.00	✓
			4,961.00	
		Less 20%	992.20	3,968.80
<b>Special Net</b>				
10 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
			40.00	40.00
<b>Labour</b>				
11 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
12 REMOVE & REFIX REAR BUMPER & ATTACHMENTS;TAILLAMP,REAR LH DOOR & ATTACHMENTS;TO CUT,WELD & RENEW REAR LH FENDER;KNOCKING & REPAIR REAR END PANEL,LH ROCKER PANEL & REALIGN BOOTLID THE SAME	900.00	1 LA	900.00	700
13 PUTTY & RESPRAY REAR BUMPER,REAR LH FENDER,LH ROCKER PANEL,REAR LH DOOR,REAR END PANEL,ROOF PANEL & ALL AFFECTED AREAS	800.00	1 LA	800.00	600
14 REMOVE & REFIX REAR LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING THE SAME	50.00	1 LA	50.00	✓
15 REMOVE & REFIX ROOF LINING TO FACILITATE REPAIR	120.00	1 LA	120.00	100
16 REMOVE & REFIX REAR SEAT,CARPET TO FACILITATE REPAIR	150.00	1 LA	150.00	100
17 REMOVE & REFIX REAR LH WHEEL,BALANCE & REALIGN THE SAME	50.00	1 LA	50.00	20
18 RUSTPROOFING	90.00	1 LA	90.00	60
			2,280.00	2,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: