

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711
 TEL: 63476100
 ATTN: Motor Claim Department
 WS Ref: TP/III/AMK
 Claim Type: Third Party
 Accident Date: 13/09/2020
 TP Veh Reg No: SHC8735A

FAX: 62247743

*Not Authorized
 11 Rep &
 Resurvey After Painting*

Estimate No: ES2090719/AMK
 Date: 14 Sep 2020
 Policy No: 5115449990 DC
 Veh Reg No: SKZ2997T
 Make/Model: MAZDA 6
 Chassis No: JM6GJ1032G0221227
 Engine No: PY20666271
 Reg. Date: 18/01/2016

6 days

Estimate Repair Cost to Vehicle No :SKZ2997T

| Description | U/Price | Quantity | List Price SS | Amount SS |
|--|----------|----------|------------------|--------------|
| List Price | | | | |
| 1 REAR LH FENDER | 1,312.00 | 1 PC | 1,312.00 | ✓ |
| 2 REAR LH FENDER QUARTER GLASS GARNISH | 263.00 | 1 PC | 263.00 | 7X |
| 3 REAR LH DOOR | 1,314.00 | 1 PC | 1,314.00 | ✓ |
| 4 REAR LH DOOR INNER LOCK | 249.00 | 1 PC | 249.00 | X |
| 5 REAR LH DOOR POWER WINDOW MOTOR | 156.00 | 1 PC | 156.00 | X |
| 6 REAR LH DOOR POWER WINDOW MOTOR REGULATOR | 149.00 | 1 PC | 149.00 | X |
| 7 REAR LH DOOR FRAME STICKER | 59.00 | 1 PC | 59.00 | ✓ |
| 8 REAR WINDSCREEN GLASS MOULDING | 118.00 | 1 SET | 118.00 | ✓ |
| 9 REAR LH RIM 17" | 1,341.00 | 1 PC | 1,341.00 | ✓ |
| | | | 4,961.00 | |
| | | Less 20% | 992.20 | 3,968.80 |
| Special Net | | | | |
| 10 REAR WINDSCREEN GLASS SEALANT | 40.00 | 1 PC | 40.00 | ✓ |
| | | | 40.00 | 40.00 |
| Labour | | | | |
| 11 REMOVE AND REFIX REAR WINDSCREEN GLASS | 120.00 | 1 LA | 120.00 | ✓ |
| 12 REMOVE & REFIX REAR BUMPER & ATTACHMENTS;TAILLAMP,REAR LH DOOR & ATTACHMENTS;TO CUT,WELD & RENEW REAR LH FENDER;KNOCKING & REPAIR REAR END PANEL,LH ROCKER PANEL & REALIGN BOOTLID THE SAME | 900.00 | 1 LA | 900.00 | 700 |
| 13 PUTTY & RESPRAY REAR BUMPER,REAR LH FENDER,LH ROCKER PANEL,REAR LH DOOR,REAR END PANEL,ROOF PANEL & ALL AFFECTED AREAS | 800.00 | 1 LA | 800.00 | 600 |
| 14 REMOVE & REFIX REAR LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING THE SAME | 50.00 | 1 LA | 50.00 | ✓ |
| 15 REMOVE & REFIX ROOF LINING TO FACILITATE REPAIR | 120.00 | 1 LA | 120.00 | }100 |
| 16 REMOVE & REFIX REAR SEAT,CARPET TO FACILITATE REPAIR | 150.00 | 1 LA | 150.00 | } |
| 17 REMOVE & REFIX REAR LH WHEEL,BALANCE & REALIGN THE SAME | 50.00 | 1 LA | 50.00 | 20 |
| 18 RUSTPROOFING | 90.00 | 1 LA | 90.00 | 60 |
| | | | 2,280.00 | 2,280.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: