



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLG1001L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

44921
SLG1001L / 20/10/2016
/ 100288
WDD2053402F363274
27491030647613
MB/MB C 180 COUPE (C205)
027 799 Diamond Whi/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	18/09/2020/ 10:51	CH	371 / Go Chee Han

Description of Goods / Services

Qty	Unit Price	Disc%	Amount
-----	------------	-------	--------

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : PNPV2017-00008210-02 // 4-9-2020
DRIVE IN/TP VEH NUMBER : 14-9-2020 // SHC284L - FIRST CAPITAL
DATE IN/DATE SURVEY:
DIRECT SETTLEMENT BY:

A BPILAB

STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH

A BPIRES

RESPRAY REAR BUMPER & TRUNK LID & END PANEL

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

A 54124001

PARTIALLY REMOVE FUSE AND RELAY MODULE IN REAR WELL COMPARTMENT FOR
NECESSARY AND INSTALL.NETT

A BPILAB

PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT

A BPILAB

TRANSFER TRUNK LID MECHANICAL & ELETRICAL COMPONENT TO NEW TRUNK LID.
NETT

S BPNSUB

SUPPLY 1 SET REAR NUMBER PLATE WITH HOUSING.NETT

A BPILAB

REMOVE & REFIT LUGGAGE COMPARTMENT,TRIM, GARNISH-
CARPET FOR NECESSARY REPAIR.NETT

A BPILAB

REMOVE CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE
WHEEL BASE & ADJUST TO VEHICLE.

Confirmed & accepted by

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLG1001L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

44921
SLG1001L / 20/10/2016
/ 100288
WDD2053402F36327A
27491030647613
MB/MB C 180 COUPE (C205)
027 799 Diamond Whi/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WF001862	Credit	18/09/2020/ 10:51	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A BPILAB								540.00
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT					1.00	1457.45	00.00	1457.45
M REAR BUMPER					1.00	349.10	00.00	349.10
M LOWER BLACK TRIM BUMPER					1.00	264.29	00.00	264.29
M REAR BUMPER CHROME MOULDING					1.00	89.59	00.00	89.59
M LH/TAILO PIPE BRACKET					1.00	126.22	00.00	126.22
M REAR SWITCH MODULE CODE A					1.00	126.22	00.00	126.22
M REAR SWITCHING MODULE CODE B					1.00	318.51	00.00	318.51
M REAR SWITCHING MODULE					1.00	43.07	00.00	43.07
M REAR SWITCHING MODULE BRACKET					1.00	153.05	00.00	153.05
M ELECTRICAL WIRING HARNESS					1.00	29.00	00.00	29.00
M LEFT REFLECTOR LENSE					1.00	29.00	00.00	29.00
M RIGHT REFLECTOR LENSE					1.00	108.57	00.00	108.57
M CTR/LOWER COVER BUMPER AREA					1.00	37.82	00.00	37.82
M LH/BOTTOM BRACKET					1.00	38.23	00.00	38.23
M RH/BOTTOM BRACKET					1.00	27.08	00.00	27.08
M LH/DAMPING, SIDE WALL					1.00	24.16	00.00	24.16
M RH/DAMPING, SIDE WALL					1.00	45.90	00.00	45.90
M RIVET FOR BUMPER					10.00	4.59	00.00	45.90
M DISTANCE SENSOR					2	178.75	00.00	715.00
M SPACER RING					6.00	6.35	00.00	38.10
M TRUNK LID					1.00	2273.75	00.00	2273.75
M BOTTOM RETAINER WEDGE					2.00	26.83	00.00	53.66
M TOP SPRING DAMPER					2.00	10.15	00.00	20.30
M TRUNK LID SEALING FRAME					1.00	197.91	00.00	197.91
M LH/TRUNK LID HINGE					1.00	268.75	00.00	268.75
M RH/TRUNK LID HINGE					1.00	268.75	00.00	268.75
M C180 MODEL PLATE					1.00	91.04	00.00	91.04
M TRUNK LID MERCEDES STAR					1.00	95.12	00.00	95.12
M GROMMET					3.00	2.61	00.00	7.83
M TRIM, TRUNK SILL					1.00	144.66	00.00	144.66
M REAR CROSS MEMBER					1.00	712.25	00.00	712.25
M RH/LOWER COVER, REAR-END FLOOR					1.00	50.95	00.00	50.95

Confirmed & accepted by

Go Chee Han

DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarrage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



**Cycle & Carriage
Industries Pte Limited**
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLG1001L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

WIP No

Vehicle & Document Information

44921

Reg No/Reg Date

SL G1001L / 20/10/2016

Date In/Mileage

100288

Chassis No

WDD2053402F363274

Engine No

27491030647613

Make/Model

MB/MB C 180 COUPE (C205)

Colour/Trim

027 799 Diamond Whi/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WF001862	Credit	18/09/2020/ 10:51	CH	371 / Go Chee Han				
Description of Goods / Services								
M	SPARE WHEEL RECESS	BR			1.00	562.25	00.00	562.25
M	WATER DRAIN GROMMET	MC			1.00	5.25	00.00	5.25
M	EXPANSION RIVET	MC			8.00	5.87	00.00	46.96
M	REAR END PANEL	MC			1.00	1166.28	00.00	1166.28
M	BLIND RIVET 6.4 X 12	MC			14.00	1.35	00.00	18.90
M	BLIND RIVET W CSK. HEAD	MC			6.00	1.95	00.00	11.70
M	ONE-COMPONENT ADHESIVE	MC			1.00	156.83	00.00	156.83
M	TS TWO-COMPONENT ADHESIVE	MC			1.00	776.81	00.00	776.81
M	TWO-COMPONENT ADHESIVE	MC			1.00	102.00	00.00	102.00
M	WHITE SEAM SEALING COMPOUND	MC			1.00	104.99	00.00	104.99
M	LICENSE PLATE LAMP	BR			2.00	27.46	00.00	54.92
M	LH/REAR SHIELDING	BT			1.00	164.36	00.00	164.36
M	LEFT OUTER REAR LAMP COMBINATION	BT			1.00	630.75	00.00	630.75
M	RIGHT OUTER REAR LAMP COMBINATION	BT			1.00	630.75	00.00	630.75

Steve (LKK)
83228813

WHL Pol

18/9/20, 11.00 am

11 days

Ry BeL SN

ρ/ρ

Go Chee Han

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

	Nett	27,578.08
7% GST on	27578.08	1930.47

Total Payable 29,508.55

LKK Auto Consultants hence notify

the Repairer of the following:
Authorized signatory and company stamp
• In resurvey before/after spray painting

Validity of this estimate is 90 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs ~~parts and labour~~ ^{parts only} are based on the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. ~~Parts are discovered after work has started and needed for repairs or replacement. However, should this occur, a third party survey is on a 'Permit to Proceed' basis.~~ ^{Parts are discovered after work has started and needed for repairs or replacement. However, should this occur, a third party survey is on a 'Permit to Proceed' basis.}
we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windshield in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windshield.
~~Supplementary item(s) must be resurveyed and~~ ^{No illegal modifications is allowed}
the removal of the windshield is subject to final approval from Insurance Company

Pandan Loop Service Center

Acknowledged by Repairer

Signature:

Date: _____

Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Page: