



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLG1001L

MS FIRST CAPITAL INSURANCE LIMITED
MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

44921
SLG1001L / 20/10/2016
100288
WDD2053402F36327A
27491030647613
MB/MB C 180 COUPE (C205)
027 799 Diamond Whi/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WF001862	Credit	18/09/2020/ 10:51	CH	371 / Go Chee Han				
Description of Goods / Services								

Z REQUEST

Customer Request
M-BPNSUN
POLICY NO/ACC DATE : PNPV2017-00008210-02 // 4-9-2020
DRIVE IN/TP VEH NUMBER : 14-9-2020 // SHC284L - FIRST CAPITAL
DATE IN/DATE SURVEY:
DIRECT SETTLEMENT BY:

- A BPILAB
STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH
- A BPIRES
RESPRAY REAR BUMPER & TRUNK LID & END PANEL
- A BPILAB
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT
- A BPILAB
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT
- A 54124001
PARTIALLY REMOVE FUSE AND RELAY MODULE IN REAR WELL COMPARTMENT FOR
NECESSARY AND INSTALL.NETT
- A BPILAB
PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT
- A BPILAB
TRANSFER TRUNK LID MECHANICAL & ELETRICAL COMPONENT TO NEW TRUNK LID.
NETT
- S BPNSUB
SUPPLY 1 SET REAR NUMBER PLATE WITH HOUSING.NETT
- A BPILAB
REMOVE & REFIT LUGGAGE COMPARTMENT,TRIM, GARNISH-
CARPET FOR NECESSARY REPAIR.NETT
- A BPILAB
REMOVE CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE
WHEEL BASE & ADJUST TO VEHICLE.

3840 3860 5760.00 ✓
2729 3000.00 ✓
0.10 380.00 ✓
120.00 ✓
480.00 ✓
(photo) 0.07 1000.00 ✓
480.00 ✓
60.00 ✓
960.00 ✓
1920 2160.00 ✓

Confirmed & accepted by

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLG1001L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 44921
Reg No/Reg Date SLG1001L / 20/10/2016
Date In/Mileage 1-100288
Chassis No WDD2053402F363274
Engine No 27491030647613
Make/Model MB/MB C 180 COUPE (C205)
Colour/Trim 027 799 Diamond Whi/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	18/09/2020/ 10:51	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SPARE WHEEL RECESS	1.00	562.25	00.00	562.25
M WATER DRAIN GROMMET	1.00	5.25	00.00	5.25
M EXPANSION RIVET	8.00	5.87	00.00	46.96
M REAR END PANEL	1.00	1166.28	00.00	1166.28
M BLIND RIVET 6.4 X 12	14.00	1.35	00.00	18.90
M BLIND RIVET W CSK. HEAD	6.00	1.95	00.00	11.70
M ONE-COMPONENT ADHESIVE	1.00	156.83	00.00	156.83
M TS TWO-COMPONENT ADHESIVE	1.00	776.81	00.00	776.81
M TWO-COMPONENT ADHESIVE	1.00	102.00	00.00	102.00
M WHITE SEAM SEALING COMPOUND	1.00	104.99	00.00	104.99
M LICENSE PLATE LAMP	2.00	27.46	00.00	54.92
M LH/REAR SHIELDING	1.00	164.36	00.00	164.36
M LEFT OUTER REAR LAMP COMBINATION	1.00	630.75	00.00	630.75
M RIGHT OUTER REAR LAMP COMBINATION	1.00	630.75	00.00	630.75

ESTIMATE

Steve (LKK)
83228813

WHL PL

18/9/20, 11.00 am

11 days

Ry Bel sn

P/P

* SUPP parts

- Load compartment well \$556.81 (BR)
- Trim Panel Loading space \$72.72 (BR)
- Trim, Load compartment \$72.72 (BR)
- cable duct \$16.40 (MIS)
- Hexagon nut w collar \$10.32 (NEC)

Go Chee Han

DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

- Tapping Cream \$5.84 (NEC)

Confirmed & accepted by

Nett 27,578.08
7% GST on 27578.08 1930.47
Total Payable 29,508.55

LKK Auto Consultants hence notify

the Repairer of the following:

Authorized signatory and company stamp

Validity of this estimate is subject to the following conditions: This is a computer generated document, no signature is required. Estimated costs are based on the information provided and do not include any additional parts or labour which may be required after repair work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378



Mercedes-Benz

ESTIMATE FOR SLG1001L

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 195400367W
GST Reg No. MR-8500111-X

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 44921
Reg No/Reg Date SLG1001L / 20/10/2016
Date In/Mileage 100288
Chassis No WDD2053402F363274
Engine No 27491030647613
Make/Model MB/MB C 180 COUPE (C205)
Colour/Trim 027 799 Diamond Whi/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	18/09/2020/ 10:51	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A SPILAS				520.00
TO INSPECT & CONDUCT WHEEL ALIGNMENT NETT				
M REAR BUMPER	1.00	1457.45	00.00	1457.45
M LOWER BLACK TRIM BUMPER	1.00	349.10	00.00	349.10
M REAR BUMPER CHROME MOULDING	1.00	264.29	00.00	264.29
M LH/TAILO PIPE BRACKET	1.00	89.59	00.00	89.59
M REAR SWITCH MODULE CODE A	1.00	126.22	00.00	126.22
M REAR SWITCHING MODULE CODE B	1.00	126.22	00.00	126.22
M REAR SWITCHING MODULE	1.00	318.51	00.00	318.51
M REAR SWITCHING MODULE BRACKET	1.00	43.07	00.00	43.07
M ELECTRICAL WIRING HARNESS	1.00	153.05	00.00	153.05
M LEFT REFLECTOR LENSE	1.00	29.00	00.00	29.00
M RIGHT REFLECTOR LENSE	1.00	29.00	00.00	29.00
M CTR/LOWER COVER BUMPER AREA	1.00	108.57	00.00	108.57
M LH/BOTTOM BRACKET	1.00	37.82	00.00	37.82
M RH/BOTTOM BRACKET	1.00	38.23	00.00	38.23
M LH/DAMPING, SIDE WALL	1.00	27.08	00.00	27.08
M RH/DAMPING, SIDE WALL	1.00	24.16	00.00	24.16
M RIVET FOR BUMPER	10.00	4.59	00.00	45.90
M DISTANCE SENSOR	2	178.75	00.00	357.50
M SPACER RING	6.00	6.35	00.00	38.10
M TRUNK LID	1.00	2273.75	00.00	2273.75
M BOTTOM RETAINER WEDGE	2.00	26.83	00.00	53.66
M TOP SPRING DAMPER	2.00	10.15	00.00	20.30
M TRUNK LID SEALING FRAME	1.00	197.91	00.00	197.91
M LH/TRUNK LID HINGE	1.00	268.75	00.00	268.75
M RH/TRUNK LID HINGE	1.00	268.75	00.00	268.75
M C180 MODEL PLATE	1.00	91.04	00.00	91.04
M TRUNK LID MERCEDES STAR	1.00	95.12	00.00	95.12
M GROMMET	3.00	2.61	00.00	7.83
M TRIM, TRUNK SILL	1.00	144.66	00.00	144.66
M REAR CROSS MEMBER	1.00	712.25	00.00	712.25
M RH/LOWER COVER, REAR-END FLOOR	1.00	50.95	00.00	50.95

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han

DID: 6771 4336 HP: 9181 7717

Email: cheehan.go@cyclecarrage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center