



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20009333/Eqf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 30-09-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3335P	Veh. Inspected	SLJ 8322Z
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20080502	Excess (\$)	0.00
Assign From	CARINE KEK	Assign Date	15/09/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104555535	Colour	GREY
Odometer	264376	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	5 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	5 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	5 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/08/2020	Inspection Date	03/09/2020
Survey held at	15 Kaki Bukit Road 4 #01-53 Bartley Biz Centre		
Repairer	RV AUTOWORKS		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**