

Hup Ley Huat Motor Spray Painting Services

No. 1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 417883

TEL: 6745 0674 FAX: 6541 7839

Vehicle No.: SMC7108H

Make: Mitsubishi Attrage 1.2 CVT

Accident Date: 11/09/2020

Spare parts

QTY	List Price	Price	(S\$)	
1	Rear Bumper	659.00		de✓
2	Rear Bumper Retainer LH/RH	44.00		de✓
2	Rear Bumper Reflector	44.00		cr✓
1	Rear Tail Lamp LH	266.00		an✓
1	Rear Tail Lamp RH	266.00		an✓
1	Rear BootLid	752.00		bt✓
1	Rear BootLid Garnish	318.00		an✓
1	Rear BootLid Lock	198.00		bt✓
1	Rear Boot Key Lock Switch	79.00		an✓
1	Rear Sensor	75.00		an✓
1	Bootlid Weather Strip	143.00		an✓
1	Rear End Panel	402.00		bt✓
1	Rear End Panel Trim	62.00		de✓
1	Rear Emblem Set	41.00		an✓
1	RHS Trunk Side Trim	158.00		x nn
1	LHS Trunk Side Trim	158.00		x nn
1	Trunk Room Floor Carpet	177.00		de✓
1	Rear floor panel	987.00		x R✓
1	Fender LHS	725.00		R✓
1	Fender RHS	725.00		R✓
1	LHS Rear Wheelhouse Shield	35.00		an✓
1	RHS Rear Wheelhouse Shield	35.00		an✓
1	BootLid Hinge LH	185.00		R✓
1	BootLid Hinge RH	185.00		R✓
1	Under-Body Shield Clip	2.00		x nn
4	Wheel House Shield Clip	8.00		an✓
4	Tail Lamp Clip	8.00		an✓
Spare Parts Subtotal		6737		

Labour charges

S/N		(S\$)	
1	Spray Painting	1800	1200.
1	To tuff coat affected areas	200	80.
2	Panel beating/ Welding + Realignment	2200	1000.
Labour charges: Subtotal		4200	

3609
10% = 3248.10.

Special Next Items

S/N		(S\$)	
1	Rear Bumper Lower garnish	900	Can ✓ 450
1	Rear Number Plate	105	X 200
1	Rear Camera	150	X 100
1	Towing	120	X 100
Labour charges: Subtotal		1275	2730

ESTIMATES PARTS AND LABOR GRAND TOTAL:

\$12212.00

Tanpin 4749579
 WP 16/9/20.
 L/S Resurvey after repair.
 7 days
 Tanpin @ Huantrac.

3248.10
 2730
 5978.10
 L/S \$ 4800
 7 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: