

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG20009908/R1EA3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100310930
<b>Claimant Vehicle No :</b>	SMQ7771T	<b>Insured Vehicle No :</b>	SCM9995R
Date of Loss:	19/06/2020	Nature of Claim:	TP
		Claim No:	2641754311SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMQ7771T</b>	Engine No:	CYP002095
Make & Model:	AUDI A6, 2.0 TFSI (A)	Chassis No:	WAUZZZ4G5FN063175
Reg. Date:	28/05/2015 (Man. Year: 2015)	Odometer:	54009 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,218.00	4,166.56	6,051.44	59.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,632.00	3,152.00	3,480.00	52.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,850.00</b>	<b>7,318.56</b>	<b>9,531.44</b>	<b>56.57</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,179.50</b>	<b>512.30</b>	<b>667.20</b>	<b>56.57</b>
<b>Nett Amount (S\$)</b>	<b>18,029.50</b>	<b>7,830.86</b>	<b>10,198.64</b>	<b>56.57</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>8,332.86</b>		

INSPECTION

Date of Assignment:	15/09/2020		
Date Inspected:	17/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FLOOR DOOR	Repair	3,684.00 FS	*- FS
2	1		*FRONT DOOR STONE GUARD FILM	Necessary	119.00 FS	*95.20 FS
3	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	188.00 FS	*- FS
4	1		*FRONT DOOR OUTER SEAL	Not Necessary	228.00 FS	*- FS
5	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
6	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
7	1		*FRONT DOOR CATCH	Not Necessary	118.00 FS	*- FS
8	1		*TYRE PRESSURE DATE PLATE	Not Necessary	28.00 FS	*- FS
9	1		*REAR DOOR -RH	Bent	3,684.00 FS	*2,947.20 FS
10	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	83.00 FS	*- FS
11	1		*REAR DOOR OUTER SEAL	Necessary	228.00 FS	*182.00 FS
12	1		*BONDING AGENT	Necessary	47.00 FS	*37.60 FS
13	1		*CLEANING SOLUTION	Necessary	65.00 FS	*52.00 FS
14	1		*REAR DOOR CATCH	Serviceable	118.00 FS	*- FS
15	1		*ALUMINIUM RIM -RH REAR	Scratched	1,256.00 FS	*850.00 FS
16	1		*WHEEL RIM VALVE	Not Necessary	10.00 FS	*- FS
17	1		*SUNDRIES	Necessary	250.00 FS	*2.56 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)      10,218.00      4,166.56**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER RHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES ,INSPECT FOR DAMAGES	New	560.00	280.00
2	TO DISMANTLE AND RENEW RHS FRONT AND REAR DOOR .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,400.00	750.00
3	TO RESPRAY RHS FRONT DOOR ,RHS REAR DOOR AND RHS FENDER	New	3,200.00	1,650.00
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,632.00</b>	<b>3,152.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >