




SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	SOM02K2L
Reference	CS/ASM20009912/Dtf3e2 
Loss Date	27 March 2020
Report Date	28 Mar 2020 12:00:00 AM
Request Date	15 September 2020
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated workshop survey

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SMQ8290H
Vehicle	
Registration #	
Make	HONDA SHUTTLE 1.5G CVT SENSING
Model	HONXXX

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , 408933

Primary Contact/Insured

KOH XIN PING
BLK 684A EDGEDALE PLAINS, #16-609,
821684, Singapore
87786373

Claim Handler

WANG Peter


peter.wang@axa.com.sg

Additional Instructions

Wkshop: Specialist Auto @ Ubi Survey timing: 10:30am on Friday 18
Sep; Excess: Nil

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Add

REFERENCE #	DESCRIPTION	TOTAL AMOUNT	SUBMITTED	STATUS	PAID DATE	WITHDRAW
AC2007267	Final Invoice	\$107.00	3/11/20 11:52 AM	Waiting for Approval		

Totals

Outstanding Invoices	\$107.00	Rejected and Withdrawn	\$0.00
Payments Made	\$0.00		
Total	\$107.00		