

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP Chim.
Xonne.

14 September 2020

QUOTATION FOR ACCIDENT REPAIR OF SGP4967S TOYOTA VIOS

THIRD PARTY INSURER: CHINA TAIPING

S/No.	Parts List	Qty	Amount (\$)
1.	Rear bootlid <i>Dented</i>	1	\$ 528.00 ✓
2.	Rear bootlid "Logo" emblem	1	\$ 55.00 ✓
3.	Rear bootlid "Vios" emblem	1	\$ 58.00 ✓
4.	Rear bootlid "1.5" emblem	1	\$ 40.80 ✓
5.	Rear bootlid "E" emblem	1	\$ 37.50 ✓
6.	Rear bootlid "VVTI" emblem	1	\$ 42.50 ✓
7.	Rear bootlid no plate lamp L/R <i>Green</i>	2	\$ 90.00 +
8.	Rear bootlid no plate lamp garnish	1	\$ 205.00 +
9.	Rear bootlid hinge L/R <i>new</i>	2	\$ 97.00 +
10.	Rear bootlid weather strip <i>new</i>	1	\$ 138.00 ✓
11.	Rear bootlid mechanism lock <i>Dented</i>	1	\$ 109.70 ✓
12.	Rear bootlid lock striker <i>new</i>	1	\$ 55.00 +
13.	Rear taillamp L/R <i>new</i>	2	\$ 471.60 ✓
14.	Rear taillamp gasket L/R <i>new</i>	2	\$ 40.00 ✓
15.	Rear taillamp panel L/R <i>RH Dented</i>	2	\$ 170.60 <i>85.30</i>
16.	Rear taillamp panel clip L/R <i>new</i>	6	\$ 33.00 ✓
17.	Rear bumper <i>Dented</i>	1	\$ 480.00 ✓
18.	Rear bumper side retainer L/R <i>new</i>	2	\$ 71.20 ✓
19.	Rear end panel <i>Dented</i>	1	\$ 570.30 ✓
20.	Rear end panel garnish <i>Dented</i>	1	\$ 85.80 ✓
21.	Rear spare tyre panel <i>new</i>	1	\$ 585.00 +
22.	Rear spare tyre panel top board <i>torn</i>	1	\$ 152.70 ✓
23.	Rear spare tyre panel side board L/R <i>RH torn</i>	2	\$ 191.40 <i>95.70</i>
24.	Rear exhaust silencer box <i>new</i>	1	\$ 485.10 +
25.	Rear fender inner trim L/R <i>RH torn</i>	2	\$ 430.80 <i>215.40</i>
Subtotal before discount			\$ 5224.00
Discount 25%			\$ 1306.00
Subtotal 1			\$ 3918.00

3310.50

2482.87

S/NETT	Parts List	Qty	Amount (\$)
1.	Rear no plate <i>Dented</i>	1	\$ 30 ✓
2.	Rear no plate garnish <i>new</i>	1	\$ 50 <i>30</i>
3.	Rear bumper clip <i>new</i>	1	\$ 30 ✓
4.	Rear bumper reverse sensor <i>Dented</i>	1	\$ 350 <i>200</i>
5.	Rear end panel sealant <i>new</i>	1	\$ 50 ✓
6.	Rear end panel garnish clip <i>new</i>	1	\$ 30 <i>10</i>
7.	Rear fender inner trim board clip <i>new</i>	2	\$ 60 <i>30</i>
S/Nett Total			\$ 600.00

380

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

14 September 2020

QUOTATION FOR ACCIDENT REPAIR OF SGP4967S TOYOTA VIOS

THIRD PARTY INSURER: CHINA TAIPING

Labour

To check wiring and rectify electrical faults where necessary

~~\$ 60~~ 30

To remove and replace and reinstall rear reverse sensor

~~\$ 120~~ 50

To remove and replace exhaust pipe

~~\$ 120~~ *

To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs

~~\$ 160~~ 60

To straighten, repair, realign on front affected area and replace damaged parts

~~\$ 1000~~ 800

To spray painting on affected area

~~\$ 1000~~ 800

Total Labour Cost

\$ 2460

1740

Total Cost Of Repairs(Total cost of parts + Total labour cost) **\$ 6978.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan S
2/8 16/09/20
06 Days

total: 4602.87

2/8: 3K (Nett Value)