

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 16 Oct 2020

Preliminary Advice

Insured Vehicle No	: SMC3857E		
TP Vehicle No	: SGP4967S	Accident Date	: 13/09/2020
Make	: TOYOTA VIOS	Assignment Date	: 16/09/2020
Date of Inspection	: 16/09/2020	Est. Duration of Repair	: 6
Inspection At	: SIN YU SIN WORKSHOP (HQ) 1 KAKI BUKIT AVE 6 #01-52 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,978.00
Revised Amount	:S\$	4,602.87
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,602.87

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conduct without "prejudice" basis.