

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Sep 2020		16 Sep 2020 06:21 Edit Adj Rpt	S\$8,000.00 Edit Estimates	S\$8,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	STARK HOLDINGS INN BIKE LEASING PTE LTD		
Vehicle Reg. No.:	FBR3033S	Date of Loss:	12/09/2020 17:00 - :59 [5 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D203342C02	Policy/Cover Note No.:	DMCVSNW00043202002
Vehicle Reg. No. (Insured):	GBA6638S	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	S Three Automotive Recovery Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C, 575643 Sin Ming - Tel: 62841542 / 62841575		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/09/2020]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

*FBR3033S (SNM20D203342C02)

[GBA6638S]

TP

STARK HOLDINGS INN BIKE LEASING PTE LTD

Sep 12 2020 5:00PM

[-]

S Three Automotive Recovery Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

1 per page ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/09/20 16:23	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/10/20 16:53	General View		Load JPG	☒
2	16/10/20 16:53	General View		Load JPG	☒
3	16/10/20 16:53	General View		Load JPG	☒
4	16/10/20 16:53	General View		Load JPG	☒
5	16/10/20 16:53	General View		Load JPG	☒
6	16/10/20 16:53	General View		Load JPG	☒
7	16/10/20 16:53	General View		Load JPG	☒
8	16/10/20 16:53	General View		Load JPG	☒
9	16/10/20 16:53	General View		Load JPG	☒
10	16/10/20 16:53	General View		Load JPG	☒
11	16/10/20 16:53	General View		Load JPG	☒
12	16/10/20 16:53	General View		Load JPG	☒
13	16/10/20 16:53	General View		Load JPG	☒
14	16/10/20 16:53	General View		Load JPG	☒
15	16/10/20 16:53	General View		Load JPG	☒
16	16/10/20 16:53	General View		Load JPG	☒
17	16/10/20 16:53	General View		Load JPG	☒
18	16/10/20 16:53	General View		Load JPG	☒
19	16/10/20 16:53	General View		Load JPG	☒
20	16/10/20 16:53	General View		Load JPG	☒
21	16/10/20 16:53	General View		Load JPG	☒
22	16/10/20 16:53	General View		Load JPG	☒
23	16/10/20 16:53	General View		Load JPG	☒
24	16/10/20 16:53	General View		Load JPG	☒
25	16/10/20 16:53	General View		Load JPG	☒
26	16/10/20 16:53	General View		Load JPG	☒
27	16/10/20 16:53	General View		Load JPG	☒
28	16/10/20 16:53	Reinspection Photo		Load JPG	☒
29	16/10/20 16:53	Reinspection Photo		Load JPG	☒
30	16/10/20 16:53	Reinspection Photo		Load JPG	☒
31	16/10/20 16:53	Reinspection Photo		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20009915/KSF3S2**Date:** 28/10/2020REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00043202002
Claimant Vehicle No :	FBR3033S	Insured Vehicle No :	GBA6638S
Date of Loss:	12/09/2020	Nature of Claim:	TP
		Claim No:	SNM20D203342C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR3033S	Engine No:	HIDDEN
Make & Model:	YAMAHA AEROX GDR155A, 155cc CVT ABS	Chassis No:	MH3SG4620LJ075356
Reg. Date:	01/04/2020 (Man. Year: 2020)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/80 R14	Rear Tyre Size:	140/70 R14
Front Left Side:	IRC 5 mm	Rear Left Side:	IRC 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,501.50	9,893.90	15,607.60	61.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	490.00	2,750.00	84.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,741.50	10,383.90	18,357.60	63.87
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	28,741.50	8,000.00	20,741.50	72.17

INSPECTION

Date of Assignment:	16/09/2020	
Date Inspected:	16/09/2020	Inspected At: S Three Automotive Recovery Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C Singapore 575643
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Oct 2020)	
Parts:	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR3033S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER SIDE RH	Broken	495.00 FL	*495.00 FL
2	1		*FRONT FENDER SIDE LH	Distorted	495.00 FL	*495.00 FL
3	1		*FRONT HEADLAMP ASSY LH }	Broken	695.00 FL	*695.00 FL
4	1		*FRONT HEADLAMP ASSY RH }		695.00 FL	*- FL
5	1		*FRONT HEADLAMP STAY LH	Bent	195.00 FL	*195.00 FL
6	1		*FRONT HEADLAMP STAY RH	Bent	195.00 FL	*195.00 FL
7	1		*FRONT HEADLAMP INNER BRACKET ASSY	Bent	335.00 FL	*335.00 FL
8	1		*FRONT HEADLAMP COVER GUARD LH	Distorted	222.00 FL	*222.00 FL
9	1		*FRONT HEADLAMP COVER GUARD RH	Missing	222.00 FL	*222.00 FL
10	1		*FRONT SIGNAL LAMP RH HID	Serviceable	285.00 FL	*- FL
11	1		*FRONT SIGNAL LAMP LH HID	Serviceable	285.00 FL	*- FL
12	1		*FRONT SIGNAL LAMP HOUSING RH	Cracked	290.00 FL	*290.00 FL
13	1		*FRONT SIGNAL LAMP HOUSING LH	Mtg Cracked	290.00 FL	*290.00 FL
14	1		*FRONT WING MIRROR LH	Missing	265.00 FL	*265.00 FL
15	1		*FRONT WING MIRROR RH	Dented	265.00 FL	*265.00 FL
16	1		*FRONT WHEEL GUARD	Cracked	298.00 FL	*298.00 FL
17	1		*FRONT HANDLE BAR	Bent	395.00 FL	*395.00 FL
18	1		*FRONT HANDLE BALANCER LH	Serviceable	180.00 FL	*- FL
19	1		*FRONT HANDLE BALANCER RH	Dented	180.00 FL	*180.00 FL
20	1		*FRONT HANDLE GRIP LH	Serviceable	170.00 FL	*- FL
21	1		*FRONT HANDLE GRIP RH	Torn	170.00 FL	*170.00 FL
22	1		*FRONT BRAKE LEVER	Dented	56.00 FL	*56.00 FL
23	1		*FRONT STEP COVER RH	Dented / Cut	395.00 FL	*395.00 FL
24	1		*FRONT STEP COVER LH	Mtg Cracked	395.00 FL	*395.00 FL
25	1		*FRONT FENDER INNER COVER LH	Serviceable	330.00 FL	*- FL
26	1		*FRONT FENDER INNER COVER RH	Cracked	330.00 FL	*330.00 FL
27	1		*FRONT WHEEL SHAFT	Bent	465.00 FL	*465.00 FL
28	1		*SET FRONT LOWER COVER	Mtg Cracked	695.00 FL	*695.00 FL
29	1		*SET FRONT FORK ASSY	Serviceable	380.00 FL	*- FL
30	1		*SET FRONT FORK BEARING ASSY	Serviceable	275.00 FL	*- FL
31	1		*FRONT FORK STEM	Serviceable	346.00 FL	*- FL
32	1		*FRONT GLASS	Cut	198.00 FL	*198.00 FL
33	1		*SIDE STAND	Repair	97.00 FL	*- FL
34	1		*GEAR SELECTION FOOT REST	No such part	180.00 FL	*- FL
35	1		*REAR PILLION FOOT REST LH	Serviceable	180.00 FL	*- FL
36	1		*REAR PILLION FOOT REST BRACKET LH	Repair	72.00 FL	*- FL
37	1		*REAR SEAT SIDE COVER RH	Serviceable	239.00 FL	*- FL
38	1		*SPEEDOMETER	Mtg Cracked	1,200.00 FL	*1,200.00 FL
39	1		*SPEEDOMETER BRACKET	Distorted	380.00 FL	*380.00 FL
40	1		*SPEEDOMETER COVER	Cracked	320.00 FL	*320.00 FL
41	1		*RADIATOR	Serviceable	1,520.00 FL	*- FL
42	1		*RADIATOR SIDE COVER	Serviceable	180.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR EXHAUST OUTER COVER	Dented	315.00 FL	*315.00 FL
44	1		*ENGINE SIDE COVER LH	Serviceable	295.00 FL	*- FL
45	1		*ENGINE SIDE COVER RH	Dented	295.00 FL	*295.00 FL
46	1		*GEAR CHAIN COVER	Serviceable	135.00 FL	*- FL
47	1		*REAR SIDE LAMP RH	Serviceable	165.00 FL	*- FL
48	1		*REAR SIDE LAMP LH	Serviceable	165.00 FL	*- FL
49	1		*REAR EXHAUST PIPE (LOCAL REPAIR)	Dented	2,070.00 FS	*350.00 FS
50	1		*FRONT SPORT RIM	Serviceable	1,560.00 FS	*- FS
51	1		*FRONT TYRE	Serviceable	380.00 FS	*- FS
52	1		*ERP UNIT	Serviceable	156.00 FS	*- FS
53	1		*ERP BRACKET	Repair	25.00 FS	*- FS
54	1		*FRONT FORK OIL	Not Necessary	20.00 FS	*- FS
55	1		*FRONT NO. PLATE	Dented	18.00 FS	*18.00 FS
56	1		*COOLANT	Not Necessary	30.00 FS	*- FS
57	1		*HELMET	Serviceable	120.00 FS	*- FS
58	1		*SET HORN	Serviceable	120.00 FS	*- FS
59	1		*BODY STRIKER ASSY	Necessary	800.00 FS	*200.00 FS
60	1		*REAR TOP BOX	Dented / Cut	280.00 FS	*280.00 FS
61	1		*REAR TOP BOX CARRIER	Repair	180.00 FS	*- FS
62	1		*GPS HOLDER SEAT	Serviceable	180.00 FS	*- FS
63	1		*GPS SYSTEM	Serviceable	4,680.00 FS	*- FS
64	1		*FOOD DELIVERY BAG	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,124.00	10,899.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,622.50	1,005.10
Total Parts (\$\$)	25,501.50	9,893.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS.	New	700.00	200.00
2	SPRAY PAINTING ON ACCIDENT AREAS.	New	700.00	0.00
3	CONDUCT FULL WHEEL ALIGNMENT. }	New	120.00	120.00
4	CONDUCT CHASSIS ALIGNMENT. }	New	180.00	0.00
5	TRANSPORT BIKE TO WORKSHOP.	New	80.00	30.00
6	CHECK & REPAIR WIRING SYSTEM.	New	120.00	20.00
7	BALANCE FRONT WHEEL.	New	50.00	0.00
8	BALANCE REAR WHEEL.	New	50.00	0.00
9	PRESS FRONT FORK WHEEL TO CENTRE ALIGN.	New	380.00	0.00
10	TOWING CHARGES.	New	180.00	0.00
11	PRESS REAR CHASSIS REAR FORK TO CENTRALISE.	New	680.00	120.00
Gross Labour Cost (S\$)			3,240.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >