

TP Chiu.  
Shirley.

SJE : \_\_\_\_\_  
Date of Survey : \_\_\_\_\_  
Contacts : \_\_\_\_\_

Vehicle Nos : FBG 9673M  
Model : Yamaha XA125  
Year : \_\_\_\_\_

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

| Nos. | PARTS                                         | Qty | Unit S\$  | TOTAL S\$ |
|------|-----------------------------------------------|-----|-----------|-----------|
| 1    | Headlamp <i>Re new</i>                        | 1   | \$ 450.00 | \$ 450.00 |
| 2    | Headlamp bracket <i>new</i>                   | 1   | \$ 145.30 | \$ 145.30 |
| 3    | Headlamp cowling <i>lit.</i>                  | 1   | \$ 165.00 | \$ 165.00 |
| 4    | Front fender <i>lit.</i>                      | 1   | \$ 155.00 | \$ 155.00 |
| 5    | Fork stem <i>Best</i>                         | 1   | \$ 185.00 | \$ 185.00 |
| 6    | Fork wheel bearing <i>new</i>                 | 1   | \$ 125.00 | \$ 125.00 |
| 7    | Fork assy <i>set</i>                          | 1   | \$ 675.00 | \$ 675.00 |
| 8    | Side mirror (set) <i>LH cut</i>               | 2   | \$ 85.00  | \$ 170.00 |
| 9    | Handlebar <i>new</i>                          | 1   | \$ 288.00 | \$ 288.00 |
| 10   | Handlebar grip (set) <i>new</i>               | 1   | \$ 85.00  | \$ 85.00  |
| 11   | Handle bar balancer (set) <i>LH Missing</i>   | 1   | \$ 85.00  | \$ 85.00  |
| 12   | Signal light Front <i>lit.</i>                | 1   | \$ 65.00  | \$ 65.00  |
| 13   | Signal light Rear <i>3 new</i>                | 1   | \$ 65.00  | \$ 65.00  |
| 14   | Signal light bracket <i>3 new</i>             | 1   | \$ 135.00 | \$ 135.00 |
| 16   | Brake lever <i>LH cut</i>                     | 2   | \$ 75.00  | \$ 150.00 |
| 17   | Front fairing <i>lit.</i>                     | 1   | \$ 185.00 | \$ 185.00 |
| 18   | Lower front fairing L+R <i>LH cut.</i>        | 2   | \$ 165.00 | \$ 330.00 |
| 19   | Lower front right fairing (matte) <i>lit.</i> | 1   | \$ 94.50  | \$ 94.50  |
| 20   | Brake stand <i>3 new</i>                      | 1   | \$ 75.00  | \$ 75.00  |
| 21   | Main stand                                    | 1   | \$ 75.00  | \$ 75.00  |
| 22   | Rear Lamp <i>new</i>                          | 1   | \$ 136.00 | \$ 136.00 |
| 23   | Rear Fender <i>new</i>                        | 1   | \$ 85.30  | \$ 85.30  |
| 24   | Rear Tail Gate <i>new</i>                     | 1   | \$ 48.60  | \$ 48.60  |
| 25   | Rear Rim <i>new</i>                           | 1   | \$ 138.20 | \$ 138.20 |
| 22   | Middle fairing <i>lit.</i>                    | 1   | \$ 105.70 | \$ 105.70 |
| 23   | Rear fairing <i>lit.</i>                      | 1   | \$ 145.00 | \$ 145.00 |
| 24   | Pillion stand <i>new</i>                      | 1   | \$ 75.00  | \$ 75.00  |
| 25   | Exhaust <i>new</i>                            | 1   | \$ 616.00 | \$ 616.00 |

210520.  
1894.68

Parts Sub Total : \$ 5,052.60  
Discount 10% : \$ 505.26  
**PARTS TOTAL : \$ 4,547.34**

| Nos. | SPECIAL NETT                   | Qty | Unit S\$  | TOTAL S\$ |
|------|--------------------------------|-----|-----------|-----------|
| 1    | License plate <i>Best</i>      | 1   | \$ 18.00  | \$ 18.00  |
| 2    | IU Unit <i>new</i>             | 1   | \$ 180.80 | \$ 180.80 |
| 5    | Basket <i>new</i>              | 1   | \$ 100.00 | \$ 100.00 |
| 6    | Tailbox <i>cracked</i>         | 1   | \$ 250.00 | \$ 250.00 |
| 7    | Tailbox bracket <i>cracked</i> | 1   | \$ 165.00 | \$ 165.00 |
| 8    | Helmet <i>new</i>              | 1   | \$ 250.00 | \$ 250.00 |

358

**SPECIAL NETT TOTAL : \$ 963.80**

| Nos. | LABOUR                                                                             | S\$       |
|------|------------------------------------------------------------------------------------|-----------|
| 1    | To R&R accident damage parts, to cut/weld knock and realign accident affected area | \$ 500.00 |
| 2    | To putty and respray accident affected area                                        | \$ 500.00 |
| 4    | To check wheel alignment                                                           | \$ 75.00  |

|                |                            |    |          |
|----------------|----------------------------|----|----------|
| 5              | To check chassis alignment | \$ | 85.00    |
| LABOUR TOTAL : |                            | \$ | 1,160.00 |

|                      |           |                 |
|----------------------|-----------|-----------------|
| PARTS TOTAL :        | \$        | 4,547.34        |
| SPECIAL NETT TOTAL : | \$        | 963.80          |
| LABOUR TOTAL :       | \$        | 1,160.00        |
| <b>TOTAL :</b>       | <b>\$</b> | <b>6,671.14</b> |
| Deduct 20% :         | \$        | 1,334.23        |
| <b>GRAND TOTAL :</b> | <b>\$</b> | <b>5,336.91</b> |

575

Adrian Lj  
L/s 16/09/20

04Days

total: 2827.68

L/s: 2K (Nett Value)

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: