

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009916/ASF3Q2

Date: 03/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00047812000

Claimant Vehicle No : FBG9673M **Insured Vehicle No :** SLP4572M

Date of Loss: 12/08/2020 Nature of Claim: TP Claim No: SNM20D202874/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG9673M	Engine No:	E3K7E002851
Make & Model:	YAMAHA XA CVT, 125cc	Chassis No:	LYMKE1884C0002853
Reg. Date:	22/01/2013 (Man. Year: 2012)	Odometer:	37510 km
Colour:	Silver		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/90 R10	Rear Tyre Size:	110/90 R10
Front Left Side:	IRE 6 mm	Rear Left Side:	IRE 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,511.14	2,293.18	3,217.96	58.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	575.00	585.00	50.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,671.14	2,868.18	3,802.96	57.01
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	6,671.14	2,000.00	4,671.14	70.02

INSPECTION

Date of Assignment: 16/09/2020

Date Inspected: 16/09/2020 Inspected At:

Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Nov 2020)	
Parts:	N/A	YAMAHA XA CVT 125cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG9673M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Not Necessary	450.00 FL	*- FL
2	1		*HEADLAMP BRACKET	Not Necessary	145.30 FL	*- FL
3	1		*HEADLAMP COWLING	Cut	165.00 FL	*165.00 FL
4	1		*FRONT FENDER	Cut	155.00 FL	*155.00 FL
5	1		*FORK STEM	Bent	185.00 FL	*185.00 FL
6	1		*FORK WHEEL BEARING	Not Necessary	125.00 FL	*- FL
7	1		*FORK ASSY	Bent	675.00 FL	*675.00 FL
8	1		*SET SIDE MIRROR	N/S Cut	170.00 FL	*85.00 FL
9	1		*HANDLEBAR	Not Necessary	288.00 FL	*- FL
10	1		*SET HANDLEBAR GRIP	Not Necessary	85.00 FL	*- FL
11	1		*SET HANDLE BAR BALANCER	N/S Missing	85.00 FL	*50.00 FL
12	1		*SIGNAL LIGHT FRONT	Cut	65.00 FL	*65.00 FL
13	1		*SIGNAL LIGHT REAR	Not Necessary	65.00 FL	*- FL
14	1		*SIGNAL LIGHT BRACKET	Not Necessary	135.00 FL	*- FL
15	1		*BRAKE LEVER	N/S Cut	150.00 FL	*75.00 FL
16	1		*FRONT FAIRING	Cut	185.00 FL	*185.00 FL
17	1		*LOWER FRONT FAIRING L+R	N/S Cut	330.00 FL	*165.00 FL
18	1		*LOWER FRONT LH FAIRING (MATTLE)	Cut	94.50 FL	*94.50 FL
19	1		*BRAKE STAND	Not Necessary	75.00 FL	*- FL
20	1		*MAIN STAND	Not Necessary	75.00 FL	*- FL
21	1		*REAR LAMP	Not Necessary	136.00 FL	*- FL
22	1		*REAR FENDER	Not Necessary	85.30 FL	*- FL
23	1		*REAR TAIL GATE	Not Necessary	48.60 FL	*- FL
24	1		*REAR RIM	Not Necessary	138.20 FL	*- FL
25	1		*MIDDLE FAIRING LH	Cut	105.70 FL	*105.70 FL
26	1		*REAR FAIRING LH	Cut	145.00 FL	*145.00 FL
27	1		*PILLION STAND	Not Necessary	75.00 FL	*- FL
28	1		*EXHAUST	Not Necessary	616.00 FL	*- FL
29	1		*LICENSE PLATE	Bent	18.00 FS	*18.00 FS
30	1		*IU UNIT	Not Necessary	180.80 FS	*- FS
31	1		*BASKET	Not Necessary	100.00 FS	*- FS
32	1		*TAILBOX	Cracked	250.00 FS	*250.00 FS
33	1		*TAILBOX BRACKET	Cracked	165.00 FS	*90.00 FS
34	1		*HELMET	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,016.40	2,508.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	505.26	215.02
Total Parts (\$\$)	5,511.14	2,293.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO R&R ACCIDENT DAMAGE PARTS ,TO CUT /WELD KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	500.00	250.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	500.00	250.00
3	TO CHECK WHEEL ALIGNMENT	New	75.00	75.00
4	TO CHECK CHASSIS ALIGNMENT	New	85.00	0.00
Gross Labour Cost (\$\$)			1,160.00	575.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >