



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE PTE LTD 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Chung De Rong Jonathan ADDRESS : Blk 450b Bkt Batok West Avenue 6 #12-613 Singapore 652450 TEL : 91795131 / jonathanchung46@gmail.com		WIP : 18816 EXCESS : DATE: 7-Sep-20		
VEH NO :	SME4019R	DATE IN :		CONTACT PERSON :	Jess 63957874	
CHASSIS NO :	JM6BN22A8J0242378	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM	
MODEL :	M3	DATE REG. :	27-Sep-18	POLICY NO. :		
NATURE OF WORKS						
Parts Description						
NO	QTY			REVISED	PRICES	
1	BUMPER, REAR	1	MBPD8-50-221ABB	de ✓	996.70	
2	REFLECTOR(L), REFLEX-SIDE	1	MD350-51-5L0E nn	X	53.00	
3	BRACKET CTR, BUMPER	1	MKD53-50-251 nec	X	5.40	
4	BRACKET COR., BUMPER	1	MBHR2-50-251A nn	X	24.90	
5	TAPE, PROTECTOR @ 8.60	3	MGS1D-50-EM1A	nei	25.80	
6	REINF., REAR BUMPER	1	MB45A-50-260	Xun	564.20	
7	RETAINER(L), REAR BUMPER	1	MB63B-50-2J1B 38.00	nei	38.00 22.60	
8	RIVET @ 4.50	4	MBBM4-50-355	nei	18.00	
9	SENSOR, ULTRASONIC @ 180.80	1	MKD47-67-UC1 PR	X	180.80	
10	CORD, SHORT ULTRASONIC	1	MB64F-67-290	X	152.80	
11	COVER(L), TOWING HOOK-RR	1	MBHN1-50-EL1 BB	X	16.50	
12	FASTENER @ 3.00	4	MB45A-56-146A	nei	12.00	
13	RETAINER, SENSOR	1	MKD47-67-UC5APR	Xun	15.50	
14	GASKET(R), RR.COMB.	1	MBHN1-51-153	nei	22.00	
15	GASKET(L), RR.COMB.	1	MBHN1-51-163	nei	22.00	
TOTAL PARTS					1130.10	
					2,143.20	
TOTAL PARTS COST					2,143.20	
Labour Description						
1	MZ-BR-REAR01	TO REPLACE REAR BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			660.	1,260.00
2	MZ-SP-SREAR1	TO RESPRAY REAR BUMPER.			630.	1,260.00
3	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150	250.00

	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	✓	NETT	330.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		Xnn	250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		180.	350.00
7	SUB	SUPPLY REAR BUMPER SKIRT.	nn	X NETT	550.00
8	MZ-BR-SUNDRI	SUNDRIES.	1970.	20 NETT	100.00

TOTAL LABOUR	-	4,350.00
TOTAL PARTS	-	2,143.20
TOTAL	-	6,493.20
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR

TRANS EUROKARS PTE LTD

\$3100.10
3 days.

Authorized Signature

Tanphat 97495749
'WP' 17/9/20 @ 1140
• 3 days
Repair before paint
tanphat c.khantham.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: