

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

14/09/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Ergo

Xiao Chen

MR053ZEE106158700

Accident date: 12/09/2020

Estimated repair cost for vehicle no: SLU6576M TOYOTA ALTIS 1.6 A 09'

CHASSIS: MR053ZEE106158700

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Bumper Distorted		\$561.85 ✓
2	10	Front Bumper Clip New	\$6.50	\$65.00 30
3	1	Front Bumper Emblem Logo New		\$61.75 ✓
4	1	Front Bumper Top Rubber Not New		\$191.60 X
5	1	Front Bumper Centre Lower Garnish f all		\$182.20 X
6	1	Front Bumper Reinforcement New		\$374.40 X
7	1	Front L/H Bumper Side Retainer Dented		\$122.10 67
8	1	Front L/H Bumper Fog Lamp Cracked		\$374.10 281
9	1	Front L/H Bumper Fog Lamp Cover Not New		\$174.40 X
10	1	Front Grille New		\$381.45 X
11	1	Front Grille Inner Cracked		\$281.75 ✓
12	1	Front Resonator Box Cracked		\$325.60 141
13	1	Front Resonator Box Upper Air Duct Dented		\$186.50 68
14	1	Front Resonator Box Lower Air Duct Not New		\$98.20 X
15	1	Front L/H Head Lamp Cracked		\$625.20 ✓
16	1	Front L/H Fender Dented		\$581.90 ✓
17	1	Front L/H Fender Cowling Torn		\$182.10 ✓
18	10	Front L/H Fender Cowling Clip New	\$6.50	\$65.00 30
19	1	Front L/H Rim (Special Nett) Cut		\$680.00 450(SN)
20	1	Front L/H Tyre (Special Nett) Not New		\$350.00 X
21	1	Front L/H Lower Arm Bent		\$581.90 375
22	1	Front L/H Knuckle Arm Damaged		\$561.60 ✓
23	1	Front L/H Knuckle Arm Bearing New		\$191.80 ✓
24	1	Front L/H Shock Absorber Bent		\$381.90 ✓
25	1	Front L/H Drive Shaft f all		\$1,712.40 X
26	1	Front Steering Rack New		\$1,822.50 X

Subtotal:- \$10,663.05

442185

331638

S.N 450

Labour charges

To remove & refit front L/H undercarriage & steering rack		\$380.00 220
To check wheel alignment		\$150.00 80
To check wiring		\$100.00 30
Tuff kote		\$150.00 50
Towing fee	1330	\$150.00 50
Panel beating		\$1,200.00 500
Spray painting		\$1,200.00 400

Subtotal:- \$3,330.00

Total:- \$13,993.05

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5096.38

L/S: AK

05 Days.

AK.