

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 21 Oct 2020

Preliminary Advice

Insured Vehicle No	: GBH3696G	Accident Date	: 12/09/2020
TP Vehicle No	: SLU6576M	Assignment Date	: 16/09/2020
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 5
Date of Inspection	: 16/09/2020		
Inspection At	: CN MOTOR (HQ) 1 KAKI BUKIT AVE 6 BLK C #01-41 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,993.05
Revised Amount	:S\$	5,096.39
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,096.39
 Lump Sum Repair	 :S\$	 4,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :