

Fong Motors

1, Kaki Bukit Ave 6, #01-45/27, Autobay, Singapore 417883

Vehicle No. SKF2611L
Make/Model TOYOTA ALTIS
Year :
Chassis No. MR053REE104133013

17/9/20 DATE: 16/9/2020

email to Adrian
pending to final list

PARTS LIST

	Unit Price		
FRONT BUMPER <i>Debond</i>	\$ 698.00	\$ 698.00 561	
FRONT BUMPER FORD LAMP <i>cracked</i>	\$ 286.90	\$ 286.90	
FRONT BUMPER SIDE RETAINER <i>RH and</i>	\$ 55.80	\$ 111.60 55.80	
FRONT BUMPER CLIP <i>hec</i>	\$ 40.00	\$ 40.00	SN ✓
FRONT BUMPER REINFORCEMENT <i>xben</i>	\$ 369.80	\$ 369.80	X ✓
RH FRONT FENDER <i>Dented</i>	\$ 672.40	\$ 672.40	✓ 458
FRONT FENDER UNDERGARNISH <i>3 new</i>	\$ 263.70	\$ 263.70	X ✓
FENDER UNDERGARNISH CLIP	\$ 40.00	\$ 40.00	SN X
FRONT HEAD LAMP <i>cracked</i>	\$ 825.30	\$ 825.30	✓ 522
WIPER TANK <i>Debond</i>	\$ 148.60	\$ 148.60	✓
BONNET <i>Regis</i>	\$ 883.70	\$ 883.70	X
		\$ 4,340.00	
LABOUR CHARGE			

2550

1912.50

SN: 40

TO KNOCK AND CHANGE PARTS
TO SPRAY PAINT THE AFFECTED AREA
TUFF KOTE
TO CHECK WIRING

\$ ~~800.00~~ 500
\$ ~~800.00~~ 600
\$ ~~80.00~~ 40
\$ ~~80.00~~ 30
\$ 6,983.70

1170

FONG MOTORS

total: 3122.50

h/s: 2.5K

05 Days

2.5K

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: