

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 17th September 2020

To : LKK

Attn : Bryan

Tel :

By Fax:

VEHICLE NO : FBJ 3577G

Honda CBR 400

ACCIDENT DATE: 3rd September 2020

Description	Qty	Quotation \$
1 Handle Bar LH <i>st</i>	1	235.00 ✓
2 Clutch Lever <i>broken</i>	1	75.00 ✓
3 Front Head Cowling <i>mainly broken</i>	1	235.00 ✓
4 Head Lamp Assembly <i>broken</i>	1	550.00 ✓
5 Front Mudguard <i>broken</i>	1	255.00 ✓
6 Head Lamp Lower Guard <i>broken</i>	1	165.00 ✓
7 Front Signal L/RH <i>broken</i>	2	180.00 ✓
8 Brake Lever <i>h2</i>	1	68.00 X
9 Balancer <i>h/s cut o/s h2</i>	1 Set	1200.00 ✓ <i>90.00</i>
10 Front Side Fairing L/RH <i>cut / broken</i>	1	310.00 ✓
11 CBR Gold Emblem <i>h2</i>	1	135.00 ✓
12 Fork Tube <i>st</i>	1 Set	960.00 ✓
13 Fork Under Bracket <i>Dem</i>	1	220.00 ✓
14 Front Rim <i>h2</i>	1	320.00 X
15 Front Brake Disc <i>h2</i>	1	235.00 X
16 Wheel Shaft <i>h2</i>	1	105.00 X
17 Meter Cover <i>damaged</i>	1	258.00 ✓
18 Meter Assembly <i>h2</i>	1	1,210.00 X
19 Head Lamp Stay <i>h2</i>	1	250.00 X
20 Engine Casing <i>h/s cut</i>	1	150.00 ✓
21 Front Foot Rest <i>Dem and Dem</i>	1	85.00 ✓
22 Front Foot Rest Bracket <i>broken</i>	1	155.00 ✓
23 Rear Foot Rest Bracket <i>broken</i>	1	155.00 ✓
24 Rear Foot Peg Bracket LH <i>h2</i>	1	95.00 X
25 Gear Rod <i>st</i>	1	105.00 ✓
26 Gear Pedal <i>Dem broken</i>	1	75.00 ✓
27 LH Side Panel Inner Cowling <i>cut</i>	1	198.00 ✓

Sub-Total

6,964.00

Less 10%

696.40

Sub-Total

6,267.60

4591.00

107, 4131.90

I/We (Signature) hereby acknowledge the receipt of the above mentioned items and the amount of the quotation. I/We agree to pay the amount of the quotation to the above mentioned company within the specified period of time. I/We agree to pay the amount of the quotation to the above mentioned company within the specified period of time. I/We agree to pay the amount of the quotation to the above mentioned company within the specified period of time.

Signature: _____
 Date: _____

VEHICLE NO : FBJ 3577G

Honda CBR 400

Nett items

- 1 Towing ~~RM~~
- 2 Remove & replace neccessary parts, align & etc
- 3 Remove & replace Fork Assembly, top up Fork Oil, Front Rim & Brake Disc
- 4 Putty & respray paint work
- 5 Front Visor ~~RM~~
- 6 Horn ~~RM~~ 4/S

540.00

60.00 X
~~380.00~~ 200/-

~~250.00~~ 80/-

~~450.00~~ 180/-

250.00 X
~~150.00~~ 80/-

1 set

Sub-Total

1,540.00

Nett Total

7,807.60

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

4671.90

4/S 3200/-


S9 MOTOR TRADING PTE LTD

16/09/2025 @ 1600hrs

NA Authn

2/Sun

4 dgs.



2kk Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: