

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBJ 3577G Yr Regn: April 2014

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda CBR 400 c.c. 399Colour: Black A/C: Insured / Std / NI / NASp. Reading: 114933 T/Radio: Insured / Std / NI / NAEng/No: NC47E1000661C/No: NC471000651Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 R17R: 160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or BridgestoneFront 2 mm Rear 2 mmR/Bal. 2 mm L/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 03/09/2020 D.O.I. 16/09/2020Survey held at SG 98 Motor AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/S Front y 4/S Portion

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>III SHD 4204L</u>
<u>12/11/2020</u>	<u>John 2/S 3200/- with 4 days g</u>

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.R. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 17th September 2020

To : LKK

By Fax:

Attn : Bryan

Tel :

VEHICLE NO : FBJ 3577G

Honda CBR 400

ACCIDENT DATE: 3rd September 2020

Description	Qty	Quotation \$
1 Handle Bar LH <i>bt</i>	1	235.00 ✓
2 Clutch Lever <i>broken</i>	1	75.00 ✓
3 Front Head Cowling <i>mainly broken</i>	1	235.00 ✓
4 Head Lamp Assembly <i>broken</i>	1	550.00 ✓
5 Front Mudguard <i>broken</i>	1	255.00 ✓
6 Head Lamp Lower Guard <i>broken</i>	1	165.00 ✓
7 Front Signal L/RH <i>broken</i>	2	180.00 ✓
8 Brake Lever <i>HN</i>	1	68.00 X
9 Balancer <i>W/S cut o/s HN</i>	1 Set	180.00 90.00 ✓
10 Front Side Fairing L/RH <i>cut / broken</i>	1	310.00 ✓
11 CBR Gold Emblem <i>HN</i>	1	135.00 ✓
12 Fork Tube <i>bt</i>	1 Set	960.00 ✓
13 Fork Under Bracket <i>Dem</i>	1	220.00 ✓
14 Front Rim <i>HN</i>	1	320.00 X
15 Front Brake Disc <i>HN</i>	1	235.00 X
16 Wheel Shaft <i>HN</i>	1	105.00 X
17 Meter Cover <i>original</i>	1	258.00 ✓
18 Meter Assembly <i>HN</i>	1	1,210.00 X
19 Head Lamp Stay <i>HN</i>	1	250.00 X
20 Engine Casing <i>W/S cut</i>	1	150.00 ✓
21 Front Foot Rest <i>Dem and Dem</i>	1	85.00 ✓
22 Front Foot Rest Bracket <i>broken</i>	1	155.00 ✓
23 Rear Foot Rest Bracket <i>broken</i>	1	155.00 ✓
24 Rear Foot Peg Bracket LH <i>HN</i>	1	95.00 X
25 Gear Rod <i>bt</i>	1	105.00 ✓
26 Gear Pedal <i>Dem broken</i>	1	75.00 ✓
27 LH Side Panel Inner Cowling <i>cut</i>	1	198.00 ✓

Sub-Total 6,964.00
Less 10% 696.40
Sub-Total 6,267.60

4591.00

107, 4131.90

VEHICLE NO : FBJ 3577G

Honda CBR 400

Nett items

- 1 Towing *NAI*
- 2 Remove & replace neccessary parts, align & etc
- 3 Remove & replace Fork Assembly, top up Fork Oil, Front Rim & Brake Disc
- 4 Putty & respray paint work
- 5 Front Visor *NA*
- 6 Horn *Out 4/s*

1 set

Sub-Total

Nett Total

60.00 *X*

~~380.00~~ *200/-*

~~250.00~~ *80/-*

~~450.00~~ *180/-*

~~250.00~~ *X*

~~150.00~~ *80/-*

1,540.00

7,807.60

540.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

4671.90

4/s 3200/-

S9 MOTOR TRADING PTE LTD

16/09/2025 @ 1600 hrs

NAI Authn

2/sun

4 dgs.

R
you

2kk Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: