

ASS. REC. BY:

REF:

AIG/ 20009925/kes3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STG 883/K

Yr Regn:

04, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Porsche Cayenne c.c. 3598

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

76.983

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WP1 88892 83 LA 06874

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

14/9/20

D.O.I.

16/9/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/10 11:00 @ 6000h Confirm

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Date: 15.09.2020
Vehicle No: SJG8883K
Model: PORSCHE CAYENNE 3.6A TIPTRONIC (V6)
Chassis: WP1ZZZ92ZBLA06874
Reg.Year: 2011

Third Party Insurer: AIG
Third Party Veh No: SKW5362X
Date of Accident: 14.09.2020

*Not Authorized
Repair After Paint
11 Rm @ 6000/hr 4 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR RH <i>4008</i>	1		<i>Ry</i> \$4,255.00
2	REAR DOOR SIDE GARNISH RH	1	<i>By/may</i>	\$518.00
3	REAR DOOR SIDE GARNISH CLIPS RH	1		<i>mc</i> \$85.00
4	REAR WHEEL ARCH RH	1		<i>Do</i> \$555.00
5	REAR WHEEL ARCH CLIPS RH	1		<i>mc</i> \$50.00
6	REAR RIM RH <i>1800</i>	1		<i>Do</i> \$2,775.00
SUB TOTAL				\$8,238.00
LESS 10%				-\$823.80
PARTS TOTAL				\$7,414.20

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST, DISMANTLE ACCIDENT AREA \$600.00 *500*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC. \$700.00 *500*

LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMORY. *nn* \$200.00 *X*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. \$150.00 *100*

TO TUFF KOTE & UNDERSEAL MATERIALS *nn* \$150.00 *300 X*

TO WHEEL ALIGNMENT & BALANCING. \$180.00 *80*

VIC	<u>LKK Auto Consultants</u> hence notify the Repairer of the following:	LABOUR TOTAL	\$1,980.00
	• To resurvey before/after spray painting	TOTAL	\$9,394.20

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

