

Date: 15.09.2020
Vehicle No: SJG8883K
Model: PORSCHE CAYENNE 3.6A TIPTRONIC (V6)
Chassis: WP1ZZZ92ZBLA06874
Reg.Year: 2011

Third Party Insurer: AIG
Third Party Veh No: SKW5362X
Date of Accident: 14.09.2020

*Not Authorized
Repair After Paint
11 Day 8*

4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR RH	1		<i>By</i> \$4,255.00
2	REAR DOOR SIDE GARNISH RH	1	<i>By/may</i>	\$518.00
3	REAR DOOR SIDE GARNISH CLIPS RH	1		<i>mc</i> \$85.00
4	REAR WHEEL ARCH RH	1		<i>mc</i> \$555.00
5	REAR WHEEL ARCH CLIPS RH	1		<i>mc</i> \$50.00
6	REAR RIM RH	1		<i>mc</i> \$2,775.00
SUB TOTAL				\$8,238.00
LESS 10%				-\$823.80
PARTS TOTAL				\$7,414.20

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST, DISMANTLE ACCIDENT AREA	\$600.00	<i>500</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.	\$700.00	<i>500</i>
LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMORY.	\$200.00	<i>7</i>
LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$150.00	<i>100</i>
TO TUFF KOTE & UNDERSEAL MATERIALS	<i>nn</i> \$150.00	<i>321 x</i>
TO WHEEL ALIGNMENT & BALANCING.	\$180.00	<i>80</i>

VIC	LKK Auto Consultants hence notify the Repairer of the following:	LABOUR TOTAL	\$1,980.00
	- To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	TOTAL	\$9,394.20

Acknowledged by Repairer
Signature:
Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

