

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 17 Sep 2020

Preliminary Advice

Insured Vehicle No	: SGN9170B	Accident Date	: 09/09/2020
TP Vehicle No	: SBS6030A	Assignment Date	: 16/09/2020
Make	: MERCEDES-BENZ CITARO O530	Est. Duration of Repair	: 2
Date of Inspection	: 16/09/2020		
Inspection At	: SBS TRANSIT LTD (SOON LEE ROAD) SOON LEE ROAD SINGAPORE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,188.30
Revised Amount	:S\$	2,188.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,188.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 () Lump Sum repair

 (X) The above survey was conducted on a 'without prejudice' basis.