



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

DA/FC(SHA3209X)
DOA: 09/09/2020@1800

MS FIRST CAPITAL INSURANCE PTE LTD

15/9/2020

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SGX 9111 U - HYUNDAI ELANTRA AD 1.6 GLS AT
CHASSIS NO: KMHD841CMJU464513 (2017)

1 pc	Rear bumper mudflag / CUT	\$ 28.00
1 pc	Rear rim LH — CUT	\$ 672.00
		\$ 700.00
		\$ 140.00
	LESS 20%	\$ 560.00
	Alignment	\$ 70.00 69
	Remove necessary parts: jacking, panel beating, repair and straighten rear bumper.	\$ 250.00 100
	Putty and respray rear bumper.	\$ 250.00 200
		\$ 1,130.00
	ADD 7% GST	\$ 79.10
		\$ 1,209.10

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

Steve (LKK)

WHL P/L

18/9/20, 10.15am

3 days

L/S, My AL SHY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: