

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/MSG 20009937/uvf3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

YN55887

at Workshop m/s

Mahican

of

Insured:

YN98350

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$30k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

9236

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YN55887

Yr Regn:

24/7/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Cm

Make:

Mit center FEB71

c.c

2998

Colour

White

A/C:

Insured / Std / NI / NA

Sp.Reading

Safety Ply

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FEB71CA00072Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/75R17.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6/6

mm

R/Bal.

R/Bal.

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

14/9/20

D.O.I.

17/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2023-7-2024 \$3804 up 261868/11/20 1/5 \$16,800 confirmed with sihuai

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 12

1)

☐

: Final Report

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Transportation:

2) 9/12/20-Typist

Add Fee:

☐

: Site Insp (\$

) S + RS SI☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format: MerimenLump Sum H.B.I. (\$ 16,800)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	923E

Vehicle Details

Vehicle No.:	YN5588T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2020
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB71ER4SDEC (CBU)
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	4P10B17432
Chassis No.:	FEB71EA00072
Maximum Power Output:	-
Open Market Value:	\$31,751.00
Original Registration Date:	24 Jul 2014
First Registration Date:	24 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$1,588.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	23 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$9,883.00
COE Rebate Amount:	\$3,804.00
Total Rebate Amount:	\$3,804.00

The information contained herein is correct as at 17 Sep 2020

OK

[New Cars](#)[Used Cars](#)[Rental Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)**Post an Advertisement**

Sell it yourself! Advertise it at just

\$58 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

5/2018 Volvo V60 T2,1.5turbo,1 Owner,8" Digital Meter

Market Cheapest, Depre \$10.9k
Yearly, 3year/100k Warranty, Sta
Graded A, 100% Loan
Quality Motor StarAd

Browse by Category

Sort by Date Posted

1 vehicles

mitsubishi feb71

Advanced Search

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
			Any	Any	2014	Any	Any	

**Mitsubishi Fuso Canter FEB71****\$27,800**

\$7,940 /yr

19-Mar-2014

2,998 cc

-

Fuel Type: Diesel

1 Owner. Durable Mitsubishi 15ft Lorry With Silent Powerful Euro 5 Turbo Engine. Can Carry Up To 4.2 Tons Of Goods. Very Well Maintained And Regular Service Just Done. Cal Now.

Posted: 04-Sep-2020 Tags: 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
------	-------	-------	--------------	----------	---------	---------	---

For old advertisements, view [Expired ads](#)
[Home](#) | [New Cars](#) | [Used Cars](#) | [Rental Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars insurance. Find buy used mitsubishi feb71, mitsubishi feb71 Singapore, used mitsubishi feb71 Singapore, used mitsubishi feb71, used vehicles Singapore or e Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car la Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2020 sgCarMart, Singapore. All rights reserved.

[Compare](#)

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

Not Authorised
17/9/20
2/s \$16,800
12 days

M/S: MSIG Insurance (Singapore) Pte Ltd
 4 Shenton Way, #21-01 SGX Centre 2
 Singapore 068807

TEL: 6827 7602 FAX: 6827 2708
 ATTN: Motor Claim Department

Your Ref No: SOON LI HENG CIVIL
 Claim Type: Third Party
 Accident Date: 14/09/2020
 TP Veh Reg No: YN9835D

Estimate No: ES1700759
 Date: 14 Sep 2020
 Policy No: 5114334525-000006
 Veh Reg No: YN5588T
 Make/Model: MITSUBISHI CANTER
 FEB71ER4SDEC (CBU)
 Chassis No: FEB71EA00072
 Engine No: 4P10B17432
 Reg. Date: 24/07/2014

Estimate Repair Cost to Vehicle No : YN5588T

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Front Panel <i>Bodily</i>	2337.31	3,026.19	1 PC	3,026.19 ✓
2 " FUSO " Emblem <i>nu</i>	102.35	185.95	1 PC	185.95 ✓
3 Front Corner Panel - LH/RH <i>0/5 B20</i>	102.28	608.11	2 PC	1,216.22 1 PC
4 Front Side Mirror Stay - RH <i>11</i>		571.03	1 PC	571.03 X
5 Front Side Mirror - RH <i>11</i>		121.20	1 PC	121.20 X
6 Front Side Mirror Cover - RH <i>11</i>		107.35	1 PC	107.35 X
7 Front Windscreen Glass <i>rubber B20</i>	750	1,357.64	1 PC	1,357.64 ✓
8 Front Windscreen Glass <i>Seat twi</i>	356.54	590.46	1 PC	590.46 ✓
9 Wiper Panel <i>B20</i>	567.45	587.01	1 PC	587.01 ✓
10 Wiper Blade <i>0/5 B20</i>	90.00	145.92	2 PC	291.84 1 PC
11 Wiper Arm <i>0/5 B20</i>	112.35	136.75	2 PC	273.50 1 PC
12 Wiper Motor Assy <i>11</i>		756.81	1 PC	756.81 X
13 Wiper Link Assy <i>Bent/twi</i>	225.32	254.35	1 PC	254.35 ✓
14 Wiper Tank Assy <i>11</i>		183.21	1 PC	183.21 X
15 Front Grille <i>B20</i>	1025.21	1,326.63	1 PC	1,326.63 ✓
16 " Mit " Logo <i>nu</i>	68.00	99.05	1 PC	99.05 ✓
17 " CANTER " Logo <i>nu</i>	62.00	94.09	1 PC	94.09 ✓
18 Front Bumper <i>D.S</i>	1161.66	1,212.96	1 PC	1,212.96 ✓
19 Front Bumper Bracket <i>twi</i>	105.21 x 2 =	196.27	2 PC	210.42 392.54 ✓
20 Front Bumper Inner Bracket - LH/RH <i>twi</i>	115.25 x 2 =	235.48	2 PC	230.50 470.96 ✓
21 Headlamp Assy - LH/RH <i>0/5 CNE</i>	480.12	601.69	2 PC	1,203.38 1 PC
22 Headlamp Side - LH/RH <i>0/5 B20</i>	145.00	254.35	2 PC	508.70 1 PC
23 Headlamp Bracket - LH/RH <i>NS</i>		492.00	2 PC	984.00 X
24 Signal Lamp Assy - LH/RH <i>0/5 B20</i>	196.70	319.63	2 PC	639.26 1 PC
25 Front Door Assy - LH/RH <i>R</i>		2,401.74	2 PC	4,803.48 X
26 Front Door Seal - LH/RH <i>11</i>		509.98	2 PC	1,019.96 X
27 Front Door Pillar - RH <i>R</i>		1,839.88	1 PC	1,839.88 X
28 Front Door Inner Pillar - RH <i>R</i>		1,240.94	1 PC	1,240.94 X
29 Front Door Inner Garnish - RH <i>11</i>		1,139.04	1 PC	1,139.04 X
30 Aircond Evaporator Unit With Cooling Coil Assy <i>CNE 2650.00</i>	3,048.25	3,048.25	1 PC	3,048.25 ✓
31 Aircond Blower Assy <i>CNE</i>	980.21	1,044.48	1 PC	1,044.48 ✓
32 Aircond Suction Pipe <i>Bent/twi</i>	450.00	556.10	1 PC	556.10 ✓
33 Aircond Discharge Pipe <i>Bent/twi</i>	455.35	568.27	1 PC	568.27 ✓
34 Aircond Condensor Unit With Fan Motor Assy <i>11</i>		1,727.51	1 PC	1,727.51 X
35 Aircond Drier Unit <i>11</i>		359.47	1 PC	359.47 X
36 Aircond Condensor Unit Bracket <i>11</i>		654.76	1 PC	654.76 X

1313877

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : MSIG Insurance (Singapore) Pte Ltd
 4 Shenton Way , #21-01 SGX Centre 2
 Singapore 068807

TEL: 6827 7602 FAX: 6827 2708
 ATTN: Motor Claim Department

Your Ref No: SOON LI HENG CIVIL
 Claim Type: Third Party
 Accident Date: 14/09/2020
 TP Veh Reg No: YN9835D

Estimate No: ES1700759
 Date: 14 Sep 2020
 Policy No: 5114334525-000006
 Veh Reg No: YN5588T
 Make/Model: MITSUBISHI CANTER
 FEB71ER4SDEC (CBU)
 Chassis No: FEB71EA00072
 Engine No: 4P10B17432
 Reg. Date: 24/07/2014

Estimate Repair Cost to Vehicle No : YN5588T

Description	U/Price	Quantity	List Price	Amount
			SS	SS
37 Front Floor Mat Assy <i>11</i>	995.79	1 PC	995.79 X	
38 Dashboard Assy <i>DC/warped 1914.42</i>	2,402.34	1 PC	2,402.34 ✓	
39 Steering Wheel Assy <i>11</i>	672.54	1 PC	672.54 X	
40 Steering Column Dust Cover <i>11</i>	86.18	1 PC	86.18 X	
41 Steering Wheel Airbag <i>11</i>	1,841.21	1 PC	1,841.21 X	
42 Steering Wheel Airbag Sensor Assy <i>11</i>	420.00	1 PC	420.00 X	
43 Steering Shaft Assy <i>Bent/tw 1378.48</i>	1,589.89	1 PC	1,589.89 ✓	
44 Steering Rack Assy <i>11</i>	5,559.78	1 PC	5,559.78 X	
45 Steering Box Assy <i>su</i>	1,701.41	1 PC	1,701.41 X	
46 Brake Master Pump Assy <i>DO/JM 1850.00</i>	1,987.06	1 PC	1,987.06 ✓	
47 Power Steering Pump Tank Pipe <i>Bent/tw 185.00</i>	357.93	1 PC	357.93 ✓	
48 Power Steering Pipe <i>Bent 366.22</i>	439.61	1 PC	439.61 ✓	
49 Brake Vacuum Tank Assy <i>11</i>	501.02	1 PC	501.02 X	
50 Brake Vacuum Tank Bracket <i>11</i>	371.49	1 PC	371.49 X	
51 Brake Pipe <i>Bent 165</i>	249.25	1 PC	249.25 ✓	
52 Brake Air Pipe <i>Bent 166</i>	339.41	1 PC	339.41 ✓	
53 Air Tank Assy <i>11</i>	1,324.33	1 PC	1,324.33 X	
54 Cabin Mounting Bar <i>Bent 1507.12</i>	4,752.21	1 PC	4,752.21 ✓	
55 Cabin Mounting Bracket - LH/RH <i>tw 422.83 X 2 =</i>	941.23	2 PC <i>845.66</i>	1,882.46 ✓	
56 Clutch Master Pump <i>11</i>	2,841.61	1 PC	2,841.61 X	
57 Clutch Cylinder Pedal Assy <i>11</i>	627.97	1 PC	627.97 X	
			65,399.96	
	Less 25%		16,349.99	49,050.07

Net Price

58 Brake Fluid <i>11</i>	10.00	1 BTL	10.00 X	
59 Front Crossmember Frame <i>DIS</i>	1,800.00	1 PC	1,800.00 1100	
60 Steering Oil <i>11</i>	10.00	5 LTR	50.00 20	
61 IU Bracket <i>11</i>	40.00	1 PC	40.00 20	
62 Front Number Plate <i>DIS</i>	40.00	1 PC	40.00 14	
63 Company Advertisement Logo <i>11</i>	680.00	1 PC	680.00 200	
			2,620.00	2,620.00

Labour

64 Towing charge to remove rear shaft	150.00	1 TRIP	150.00 60	
65 Labour to remove & refit front windscreen glass ,rubber seal , IU .	180.00	1 JOB	180.00 120	
66 Labour to remove & refit dashboard assy .	200.00	1 JOB	200.00 ✓	
67 Labour to remove & refit steering wheel ,steering box ,airbag ,etc .	300.00	1 JOB	300.00 200	

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : MSIG Insurance (Singapore) Pte Ltd
 4 Shenton Way , #21-01 SGX Centre 2
 Singapore 068807

TEL: 6827 7602 FAX: 6827 2708
 ATTN: Motor Claim Department

Your Ref No: SOON LI HENG CIVIL
 Claim Type: Third Party
 Accident Date: 14/09/2020
 TP Veh Reg No: YN9835D

Estimate No: ES1700759
 Date: 14 Sep 2020
 Policy No: 5114334525-000006
 Veh Reg No: YN5588T
 Make/Model: MITSUBISHI CANTER
 FEB71ER4SDEC (CBU)
 Chassis No: FEB71EA00072
 Engine No: 4P10B17432
 Reg. Date: 24/07/2014

Estimate Repair Cost to Vehicle No :YN5588T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
68 Labour to adjust alignment .	50.00	1 JOB 1 ^	50.00 X	
69 Labour to remove & refit front door ,transfer parts ,realignment .	150.00	1 JOB 1 ^	150.00 X	
70 Labour to remove & refit aircon system to carry out repair .	200.00	1 JOB 1 ^	200.00 X	
71 Labour to remove & refit wiring ,garnish ,fuel box assy ,etc .	120.00	1 JOB	120.00 30	
72 Labour to remove & reset driver airbag ,sensor , belt .	200.00	1 JOB	200.00 50	
73 Labour to remove & refit aircond parts , pipe ,hose & top up aircond gas & vacuum .	380.00	1 JOB	380.00 100	
74 Labour charge to cut ,weld ,dismantle ,remove ,refit all above parts .	2,500.00	1 JOB	2,500.00 1500	
75 To spray & painting at accident dented area .	1,800.00	1 JOB	1,800.00 1200	
76 To rust proofing at accident area .	380.00	1 JOB	380.00 60	
77 Labour to check all wiring & realignment .	150.00	1 JOB 1 ^	150.00 X	
			6,760.00	6,760.00
			Total	S\$ 58,430.07
			Add GST @ 7%	4,032.00
			Total Amount Payable	S\$ 62,462.07

TOTAL: SINGAPORE DOLLAR SIXTY TWO THOUSAND FOUR HUNDRED SIXTY TWO AND CENTS SEVEN ONLY

For MAH LIAN MOTOR VEHICLE
REPAIRER

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

7-21516.67
 252
 7-16137.50
 S/W-1354
 L-3520
 21011.50