

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 16-Sep-20

INSURANCE: ALG

MODEL: HYUNDAI I40

VEHICLE NO.: SHC 8931 A


DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR FENDER (RH) <i>new</i>	1	\$2,171.40	\$2,171.40
REAR FENDER WITH HOUSING(RH) <i>new</i>	1	\$4,736.80	\$4,736.80
REAR FENDER UNDER SHIELD(RH) <i>damaged</i>	1	\$338.60	\$338.60
REAR FENDER AIR-DUCT (RH) <i>new</i>	1	\$51.60	\$51.60
REAR FENDER TRIM BOARD (RH) <i>new</i>	1	\$688.75	\$688.75
REAR WINDSCREEN MOULDING <i>new</i>	1	\$51.80	\$51.80
REAR DOOR (RH) <i>new</i>	1	\$2,201.10	\$2,201.10
REAR DOOR RUBBER (RH) <i>new</i>	1	\$185.40	\$185.40
REAR DOOR REGULATOR (RH) <i>new</i>	1	\$660.90	\$660.90
REAR DOOR POWER WINDOW MOTOR <i>new</i>	1	\$386.20	\$386.20
REAR DOOR LOCK ASSY <i>new</i>	1	\$468.20	\$468.20
REAR DOOR TRIM BOARD (RH) <i>new</i>	1	\$743.80	\$743.80
ROCKER PANEL OUTER GARNISH (RH) <i>cut / damaged</i>	1	\$732.80	\$732.80
REAR TYRE RIM (RH) <i>2 damaged</i>	1	\$650.60	\$650.60
REAR TYRE WHEEL CAP <i>cut</i>	1	\$214.20	\$214.20
REAR WHEEL BEARING ING & HUB <i>2 new</i>	1	\$724.00	\$724.00
REAR TRAILING ARM (RH) <i>2 damaged</i>	1	\$384.00	\$384.00
REAR ASSIST (RH) <i>2 damaged</i>	1	\$219.40	\$219.40
REAR SHOCK ABSORBER (RH) <i>2 damaged</i>	1	\$683.70	\$683.70
REAR SHOCK ABSORBER MOUNTING (RH) <i>new</i>	1	\$162.60	\$162.60
ABS SENSOR <i>new</i>	1	\$217.90	\$217.90
REAR CROSS MEMBER <i>new</i>	1	\$2,021.50	\$2,021.50
STABILIZER BAR <i>new</i>	1	\$199.60	\$199.60
STABILIZER LINK <i>new</i>	1	\$85.90	\$85.90
REAR UPPER ARM (RH) <i>new 2 damaged</i>	1	\$335.75	\$335.75
REAR LOWER ARM (RH) <i>2 damaged</i>	1	\$353.80	\$353.80
REAR KNUCKLE ARM (RH) <i>2 damaged</i>	1	\$545.60	\$545.60
FRONT DOOR (RH) <i>new</i>	1	\$2,256.40	\$2,256.40
SUB TOTAL			\$22,472.30
LESS 20%			\$4,494.46
DISCOUNTED TOTAL			\$17,977.84
REAR FENDER ADVERTISEMENT LOGO (RH) <i>new</i> SN	1	\$100.00	\$100.00
REAR WINDSCREEN SEALANT <i>new</i> SN	1	\$46.00	\$46.00
Rear Door Comfortdelgro & Apps Sticker(RH) <i>new</i> SN	1	\$ 80.00	\$ 80.00
REAR DOOR ADVERTISEMENT LOGO (RH) <i>new</i> SN	1	\$100.00	\$100.00
ROCKER PANEL ADVERTISEMENT(RH) <i>new</i> SN	1	\$ 120.00	\$ 120.00
REAR TYRE (RH) <i>new</i> SN	1	\$216.00	\$216.00
FRONT DOOR COLOURED COMFORT LOGO <i>new</i> SN	1	\$75.00	\$75.00
FRONT DOOR ADVERTISEMENT LOGO <i>new</i> SN	1	\$100.00	\$100.00
SUB TOTAL			\$837.00

Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	800/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	800/-
Wiring Charge	1	\$140.00	\$140.00	HH
Tuff Kote	1	\$160.00	\$160.00	60/-
Towing Charge	1	\$80.00	\$80.00	HH
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass	1	\$120.00	\$120.00	80/-
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00	150/-
Re-set Rear ABS System	1	\$400.00	\$400.00	HH
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System	1	\$200.00	\$200.00	HH
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System	1	\$200.00	\$200.00	HH
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	150/-
TOTAL LABOUR			\$5,280.00	
ESTIMATE TOTAL			\$ 24,094.84	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

16/09/2020 @ 1700hrs

Not Author

2 hours 6 days.



J. J. Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: