## **BIFROST AUTO PTE LTD**

## REPAIR ESTIMATE

DATE:	16-Sep-20		AlG
		INSURANCE:	7, 0,
MODEL:	HYUNDAI 140	<u></u>	(

VEHICLE NO .: SHC 8931 A CC4 AIG 20009 938 Dba3

The state of the s	QTY	LIST PRICE	MOUNT		
DESCRIPTION	1	\$2,171.40	\$2,171.40		ı
REAR FENDER (RH) 15/10	1	\$4,736.80	\$4,736.80	1×	
REAR FENDER WITH HOUSING(RH) HA REAR FENDER UNDER SHIELD(RH) DO 169.30	1	\$338:60	\$338.60		
REAR FENDER UNDER SHIELD(RH) 2017/0000 1617/0000	1	\$51.60	\$51.60		ı
REAR FENDER TRIM BOARD (RH) 3 HH	1	\$688.75	\$688.75		
REAR WINDSCREEN MOULDING Nec	1	\$51.80	\$51.80		
REAR DOOR (RH) Suc	1	\$2,201.10	\$2,201.10		
REAR DOOR RUBBER (RH) 5/4	1	\$185.40	\$185.40		
REAR DOOR REGULATOR (RH) 2: 14	1	\$660.90	\$660.90		
REAR DOOR POWER WINDOW MOTOR	1	\$386.20	\$386.2		
REAR DOOR LOCK ASSY HA	1	\$468.20	\$468.2		
REAR DOOR TRIM BOARD (RH)	1	\$743.80	\$743.8		
ROCKER PANEL OUTER GARNISH (RH) Cut   defined	1	\$732.80			_
REAR TYRE RIM (RH) 2 dishard \$25.30	1	\$650.60		,0	
REAR TYRE WHEEL CAP ( )	1	\$214.20			
REAR WHEEL BEARING ING & HUB 2 2 ~ 362.00	1	\$724.00			
REAR TRAILING ARM (RH) 2 du shoul	1	\$384.00		-	
REAR ASSIST (RH) Zushih	1	\$219.40			
REAR SHOCK ABSORBER (RH) Z MShow 341.80	1	\$683:70		_	
REAR SHOCK ABSORBER MOUNTING (RH)	1	\$162.60			
ABS SENSOR HA	1	\$217.9		_	
REAR CROSS MEMBER HA	1	\$2,021.5		.50	,
STABILIZER BAR NH	1	\$199.6			ì
STABILIZER LINK	1	\$85.9			
REAR UPPER ARM (RH) - Z distro-	1	\$335.7			
REAR LOWER ARM (RH) 2 Ay	1	\$353.8		3.80	
REAR KNUCKLE ARM (RH) 7 215	1	\$545.6		5.60	
FRONT DOOR (RH)	1	\$2,256.	40 \$2,25	6.40	X
FRONT DOOR (KIT)					
SUB TOTAL 8501.15			\$22,47	2.30	
002 10 11 2			\$4,49	4.46	
LESS 20%	20 2000		\$17,97	77.84	
DISCOUNTED TOTAL 6640.92	Sec Transfer				
	N 1	\$100	00 \$1	00.00	
REAR FEINDEIL ADVEITHGEMENT TO THE				46.00	
REAR WINDSCILLINGEND IIV	N 1			80.00	١
Rear Door Comfortdelaro & Apps Sticker(RH)	N 1				١
REAR DOOR ADVERTISEMENT LOGO (RH) しんし : S	SN 1			00.00	ł
ROCKER PANEL ADVERTISEMENT(RH)	N 1			20.00	٧.
REAR TYRE (RH) 44	SN 1			216.00	-
FRONT DOOR COLOURED COMFORT LOGO	SN 1			\$75.00	-
FRONT DOOR ADVERTISEMENT LOGO HELE	SN	1 \$10	0.00 \$	100.00	1
PROBLEMENT FOR					
SUB TOTAL 621.00				837.00	)
SUB TOTAL 60-1:00					

ESTIMATE TOTAL	, v = ,	
	\$ 24,094	.84
TOTAL LABOUR	\$0,23	
	\$5,28	0.00
Diagnostic & Resetting To Erase Fault Code	1 \$550.00 \$ <del>55</del>	<del>5.55</del>
our Wheel Alignment		0.00
Re-set Rear Power Window System	4200	0.00 <del>0.00</del>
ransfer of Door Mechanism REAR 2300.00		0.00
e-set Frt Power Window System	WEST, CO.	0.00
ransfer of Door Mechanism FRONT	V. C.	0:00
e-set Rear ABS System		0.00
emove/Refix Undercarriage (RR)		اِنا 0 <del>0.0</del> 0
emove/Refix Rear Windscreen Glass		0.00
emove/Refix Cushion & Upholstery Rear		<del>0:00</del>
auting Charge		0.00
uff Kote		<del>0.0</del> 0 6
viring Charge		0.00
and Palliang	1 \$1,200.00 \$1,20	0.00
ahour Beating anel Beating Charge	1 \$1,400.00 \$1,40	0.00
hour Charge		
Labour Charge		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

16/09/2020 1700ms NA ANDW 1/5mm 6 days.

1KK Audo

9561.92 4576501-

> LKK Auto Consultants hence notify the Repairer of the following:
>
> • To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: