

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 01 Oct 2020

Preliminary Advice

Insured Vehicle No	: SLN8839D		
TP Vehicle No	: SHA9807E	Accident Date	: 15/09/2020
Make	: HYUNDAI AE IONIQ HEV FL	Assignment Date	: 16/09/2020
Date of Inspection	: 16/09/2020	Est. Duration of Repair	: 5
Inspection At	: BIFROST AUTO PTE LTD (SIN MING) (HQ) BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,122.76
Revised Amount	:S\$	13,730.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,730.52

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.