

Survey & repair  
22/09 @ 10-12

Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

318, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

16 SEP 2020

**E S T I M A T E**

|   |                   |
|---|-------------------|
| Estimate No. : b1 56023                                 | Page No. : 1 of 5 |
| Date Estimated : 16/09/2020                             |                   |
| Prepared By : <del>Brandon Chan Eng Meng</del> INTHEKAN |                   |

|  |   |
|--|---|
| <p>- ESTIMATE REPAIR FOR -<br/>Poologasundram Sri Hari<br/>21 Anderson Road<br/>#04-01. Royal Oak Residence<br/>Singapore 259984</p> | <p>- ACCOUNT - 219<br/>India Int'L Insurance Pte Ltd<br/>64 Cecil Street<br/>#04-05 IOB Building<br/>Singapore 049711</p> |
|--|---|

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------|---------|
| SLV3486D  | WBAJA12030BJ18629 | 28/12/2017 | 5201  | 0       |

| DESCRIPTION   | VALUE           |
|---|-----------------|
| To replace rear bumper, rear bumper carrier, attachment item cause by accident.   | 850 1,275.00    |
| To painting rear bumper.  | 934 1,038.00    |
| To check electrical wiring systems and lightings at the rear section for proper function.                                   | 159 177.00      |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function. | 150 177.00      |
| Sundries  | ? 80.00         |
| <b>Total Labour 1:</b>  | <b>2,747.00</b> |

| DESCRIPTION                          | QTY | PRIC     | VALUE           |
|--------------------------------------|-----|----------|-----------------|
| REAR BUMPER CARRIER                  | 1   | 862.10   | 862.10          |
| REAR BUMPER TRIM STRIP               | 1   | 105.70   | 105.70          |
| REAR BUMPER TOWING EYE FLAP PRIMED   | 1   | 52.60    | 52.60           |
| REAR BUMPER PANEL PRIMED (PDC/PMA)   | 1   | 1,619.15 | 1,619.15        |
| REAR RH REAR REFLECTOR               | 1   | 38.85    | 38.85           |
| ULTRASONIC SENSOR BLACK              | 1   | 249.95   | 249.95          |
| ULTRASONIC SENSOR BLACK              | 2   | 249.95   | 499.90          |
| DECOUPLING RING PDC TORQUE CONVERTER | 3   | 5.10     | 15.30           |
| <b>Total Parts :</b>                 |     |          | <b>3,443.55</b> |

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
 Toll-Free Number (1800-2255269)



303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

|  |                          |
|--|--------------------------|
| Estimate No. : <b>b1 56023</b>             | Page No. : <b>2 of 5</b> |
| Date Estimated : <b>16/09/2020</b>         |                          |
| Prepared By : <b>Brandon Chan Eng Meng</b> |                          |

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------|---------|
| SLV3486D  | WBAJA12030BJ18629 | 28/12/2017 | 5201  | 0       |

*Steve (LKK) WTL ML  
 3 dgs  
 P/P  
 28/9/20, 10.45 am  
 Ry P/L Sj*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

|  |                |   |          |
|--|----------------|---|----------|
|  | Labour 1       | : | 2,747.00 |
|  | Parts          | : | 3,443.55 |
|  | Labour 2       | : | 0.00     |
|  | Excess         | : | 0.00     |
|  | Total GST @ 7% | : | 433.34   |
|  | Grand Total    | : | 6,623.89 |

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\***  
**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***