

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/PC120009941/4K93

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLG 2939A

at Workshop m/s

beam

of

Insured:

SHC1977P

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

25k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

079A

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 21057

Date / Time

Action / Instruction

Rear 478.45, mirror 575.25
cover 151.75

20/10/20 2/s \$1650 confirmed w. Li Elin

Veh No:

SLG 2939A

Yr Regn:

05, 12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(a/

Make:

Volkswagen

POLO

c.c

1390

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

135263

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW2226R2CY543780

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

hankook

Front

3

mm

Rear

4

mm

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

3

mm

L/Bal.

4

mm

D.O.A.

13/9/20

D.O.I.

13/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0.5 frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

)

TOTAL



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunus Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SLG2939A

Model : VW Polo 1.4 GTI

Damaged Area: (Front Right Side Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

not Authorized
4/5 @ 1650
Hdys.

Parts / Material :

1	Front Right Fender	Body	478.45	\$	1,101.00	✓
2	Front Right Fender Quarter Garnish	CNE		\$	96.00	✓
3	Front Right Wing Mirror Assy	CNA	575.95	\$	1,452.00	✓
4	Front Right Door Outer Glass Moulding	11		\$	245.00	X
5	Front Right Door Weather Strip	11		\$	486.00	X
6	Front Right Door	11		\$	1,145.00	X
7	Front Right A-Pillar	11		\$	Repair	X
				Parts :	\$	4,525.00
				Less Parts 10% :	\$	452.50
				Total Parts :	\$	4,072.50

Special Net Items :

Front Right Door Quarter Garnish Clips	11	\$	9.00	✓
Front Right Fender Inner Shield Clips	11	\$	60.00	✓
Front Right Door Inner Trimboard Clips	11	\$	60.00	X
		Total S/N Parts :	\$	129.00

Labour :

To Remove, Repair & Renew Front RH Affected Accident Areas	\$	1,000.00	400
To Putty, Spray Paint on Affected Accident Areas	\$	1,000.00	580
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Conduct Wheel Alignment	\$	11 150.00	X
To Remove & Install Front Right Door, Trim, Garnish	\$	11 100.00	X
To Conduct ECU Setting & Reset to Specification.	\$	11 450.00	X
To Conduct Water Leakage Test	\$	11 150.00	X
To Rust Proof Affected Areas	\$	150.00	30
Total Labour :		\$	3,050.00

TOTAL PARTS :	\$	4,072.50
TOTAL SPECIAL NET ITEM :	\$	129.00
TOTAL LABOUR :	\$	3,050.00
TOTAL REPAIR COST :	\$	7,251.50

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair
- To display damaged part(s) during resurvey
- Parts prices are subject to change
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval of LKK Auto Consultants
- To display damaged part(s) during resurvey
- To resurvey before/after repair

Acknowledged by Repairer:

Signature: _____

Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

Signature: _____

Date: _____

P-140-4
101
P-1030-36
L-1030-00
2065-36
1652

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
FINALISED AMOUNT :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	079A
Vehicle Details	
Vehicle No.:	SLG2939A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.4 GTI AT 6R19V7 5DR HID
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	CAV390863
Chassis No.:	WVWZZZ6RZCY543780
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$24,661.00
Original Registration Date:	08 May 2012
First Registration Date:	08 May 2012
Transfer Count:	1
Actual ARF Paid:	\$24,661.00 12330
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 May 2022
PARF Rebate Amount:	\$13,563.00
Intended COE Rebate Details	
COE Expiry Date:	07 May 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$48,112.00
COE Rebate Amount:	\$7,494.00
Total Rebate Amount:	\$21,057.00

The information contained herein is correct as at 16 Oct 2020

OK