

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

## AIG ASIA PACIFIC INSURANCE PTE.LTD

78 Shenton Way , #11-16 Singapore 079120

Date : 16/9/2020

Vehicle No : SKA8422C  
Chassis No : MR053HY935160536  
Make/Model : TOYOTA VIOS  
Year : 2010

Not Notified  
C1 Sur & 3200h  
Paying After Repair  
6 days

| S/N | Qty | Description                     | Unit Price | Amount    |
|-----|-----|---------------------------------|------------|-----------|
| 1   | 1pc | FRONT BONNET                    | \$ 486.30  | \$ 486.30 |
| 2   | 1pc | FRONT BONNET HIAGE LH           | \$ 75.40   | \$ 75.40  |
| 3   | 1pc | FRONT BONNET HIAGE RH           | \$ 75.40   | \$ 75.40  |
| 4   | 1pc | FRONT LOCK                      | \$ 107.40  | \$ 107.40 |
| 5   | 1pc | FRONT FENDER RH                 | \$ 397.70  | \$ 397.70 |
| 6   | 1pc | FRONT WHEEL HOUSE RH            | \$ 380.26  | \$ 380.26 |
| 7   | 1pc | FRONT HEADLAMP RH               | \$ 472.70  | \$ 472.70 |
| 8   | 1pc | FRONT BUMPER                    | \$ 457.00  | \$ 457.00 |
| 9   | 1pc | FRONT BUMPER RENTANER RH        | \$ 56.31   | \$ 56.31  |
| 10  | 1pc | FRONT SUPPORT PANAL             | \$ 599.20  | \$ 599.20 |
| 11  | 1pc | FRONT BUMPER FOG LAMP COVER RH  | \$ 78.93   | \$ 78.93  |
| 12  | 1pc | FRONT BUMPER REFORCEMENT        | \$ 340.30  | \$ 340.30 |
| 13  | 1pc | FFONT EMBLEM FENDER ( VVT-I)    | \$ 45.00   | \$ 45.00  |
| 14  | 1pc | FRONT GRILLER EMBLEM ( TOYOTA ) | \$ 35.40   | \$ 35.40  |
| 15  | 1pc | FRONT INNER SHELD FENDER RH     | \$ 144.50  | \$ 144.50 |
| 16  | 1pc | WIPER GARNISH                   | \$ 594.55  | \$ 594.55 |
| 17  | 1pc | WIPER TANK                      | \$ 146.50  | \$ 146.50 |
| 18  | 1pc | WIPER TANK MOTOR                | \$ 179.40  | \$ 179.40 |
| 19  | 1pc | FRONT TYRE WHEEL RIM RH         | \$ 456.00  | \$ 456.00 |
| 20  | 1pc | FRONT TYRE RH                   | \$ 135.00  | \$ 135.00 |
| 21  | 1pc | FRONT ABSORBER RH               | \$ 382.40  | \$ 382.40 |
| 22  | 1pc | FRONT LOWER ARM RH              | \$ 422.05  | \$ 422.05 |
| 23  | 1pc | FRONT WHEEL BEARING RH          | \$ 123.59  | \$ 123.59 |
| 24  | 1pc | FRONT KNUCKEL RH                | \$ 443.02  | \$ 443.02 |
| 25  | 1pc | FRONT ENGINE UNDER COVER RH     | \$ 144.00  | \$ 144.00 |

### Labour Charges

|    |                                                                        |             |
|----|------------------------------------------------------------------------|-------------|
| 1) | Towing fee                                                             | \$ 200.00   |
| 2) | To 4 wheel Aligment                                                    | \$ 150.00   |
| 3) | To checking wiring system                                              | \$ 100.00   |
| 4) | To apply rust - proofing on effected area                              | \$ 100.00   |
| 5) | To remove & refix undercarriage                                        | \$ 300.00   |
| 6) | To repair front potion , bonnet , bumper , fender RH & wheel house     | \$ 800.00   |
| 7) | To respray front bonnet , bumper , fender RH , fender rh n wheel house | \$ 1,000.00 |

Grand Total

\$ 9,428.31

Wega Engineering Pte Ltd

Authorised Signature

Leong Chee Kwong

Mobile No: 84917768

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: