

Not Authorized
NAN

submit to insurance.

17/9/20

Page No. 1

VEHICLE NO. SMP196E

TOYOTA PRIUS

2/s \$5100

8 days. limited repair

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Front bumper		DLS 1020.00	✓ 616.25
2	Front bumper LHS and RHS foglamp @\$450		SVC 900.00	X
2	Front bumper LHS and RHS foglamp cover @\$80		SVC 160.00	X
2	Front bumper LHS and RHS side lamp @\$320		11 640.00	X
1	Front LHS headlamp		CNE 870.00	— 725.10
1	Front LHS headlamp top panel		R 240.00	X
1	Front support panel		R 560.00	X
1	Front bonnet		Bent 950.00	✓ 925.10
2	Front RHS and LHS fender @\$680	455.10 x 2	B. d. g. m 1360.00	— 910.20
2	Front RHS and LHS fender inner splash shield @\$280		nt torn 560.00	12C 188.20
2	RHS Front and Rear Door @\$960	nt SA o/s m/pe	1920.00	12C
2	RHS Front and rear Door glass run channel rubber @\$92		11 184.00	X
2	RHS Front and rear Door black side tape @\$72		o/s n/c 144.00	12C 60.00
1	RHS Side sill (rocker panel)		R 798.00	X
1	RHS Rear fender		R 982.00	X
1	RHS Rear fender inner splash shield		11 238.00	X
1	Rear bumper		R 980.00	X
1	Rear bumper side retainer LHS		11 78.00	X
1	LHS Front shock adsorber		Bent 492.00	— 422.10
1	LHS Front wheel bearing		nt 248.00	—
2	RHS and LHS Front lower arm @\$340		RUC 680.00	—
2	RHS Front and rear shock absorber @\$492		nt o/s bu 984.00	12C 422.10
2	RHS Front and rear wheel bearing @\$248		nt o/s bu 496.00	12C
2	Front RHS and LHS wheel hub		Bent 230.00	✓
2	Front RHS and LHS link bar		SVC 65.00	X
1	Front steering rack and pinion		SVC 2150.00	X
1	Front undercarriage crossmember		SVC 680.00	X
1	Rear axle		11 1250.00	X
			12599.00	
less 25%			3149.75	25%
			9449.25	
<u>SPECIAL NETT ITEMS</u>				
2	Front fender HYBIRD emblem @\$120		nt 240.00	100
2	RHS Front and rear tyre @\$250		SVC 500.00	X
1	LHS Front tyre		SVC 250.00	X
2	RHS Front and rear sports rim @\$860		cur/bent 1720.00	500
1	LHS Front sport rim		cur/bent 860.00	250
2set	RHS front and rear door inner trim board clips		11 80.00	X
2set	RHS front and rear fender inner shield clips		11 80.00	X
2set	Front and rear bumper clips		frt n/c 80.00	30
TOTAL PARTS			13259.25	

6635.25

VEHICLE NO. SMP196E TOYOTA PRIUS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	2800.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	2200.00	1600
3	To remove and refix RHS doors fittings and components	200.00	50
4	To remove and refix rear compartment fittings, garnish etc so as to facilitate repairs for rear fender	150.00	80
5	To remove and replace front undercarriage parts	250.00	✓
6	To remove and replace rear undercarriage parts	120.00	11 X
7	To remove and replace rear axle	150.00	11 X
8	To remove and replace front cross member	150.00	11 X
9	To conduct full computerised wheel alignment test	120.00	60
10	To remove and refix a/c condenser ,radiator and top up gas	150.00	11 X
11	To perform anti-rust treatment on affected areas	280.00	100
Labour Total :		6570.00	
TOTAL (PARTS & LABOUR):		19829.25	

25,274.25#

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-4976.28

S.V - 880.00

L - 2940.00

8796.28